

BUILDING INSPECTION REPORT

Inspection No: INS-5520

Type: Electrical Rough-In

Address: 88 Maple Ave Unit 3

Inspector: D. Okafor

Result: FAIL - corrections required

Notes: Junction box not accessible, GFCI missing

Re-inspection Date: 2024-05-20