

INSPECTION REPORT

LOGGED · 14 MARCH 2026 · REF · SR-2026-0314-A1

# Roof Works · 14 Mar

FINDINGS

STATUS · Roofing membrane lifted along the north parapet after the storm; two flashings are loose and the gutter outlet is blocked. A licensed roofer should re-seal the membrane before the next rainfall to stop water entering the plant room below.

NORTH PARAPET

Membrane edge lifted over roughly four metres; ponding visible at the outlet.

NEXT STEPS Book a roofing contractor to re-seal the membrane and clear the outlet.

CAPTURED · 14 MAR 2026 · 09:12 GMT+1 · GPS · 51.50740, -0.12780 · EXIF VERIFIED

SITE LOCATION: 12 Harbour Quay, Plant Room Roof

By signing below the parties confirm the observations above describe the site as found.

CONTRACTOR: Northgate Roofing Ltd

CLIENT: Harbour Estates Management

Signature & Date \_\_\_\_\_

Signature & Date \_\_\_\_\_

SR-2026-0314-A1