



Guías de metales dependientes de la dureza (banda gris: durezas altas, >180 mg/L)


Cadmio (CDHARDNESS)



Cobre (CUHARDNESS)



Níquel (NIHARDNESS)



Plomo (HARDNESS, escalones)

