

Naples Community Superintendent's Office

Facility Condition Assessment Report



CAMPUS SUMMARY

Year Built ¹	1998
GSF ²	2,115 ³
Date of Assessment	14-Jan-2020

¹ Indicates range of dates of construction present on campus

² Only permanent and semi-permanent facilities are included

³ This GSF represents DoDEA's allocation and NOT the total size of the building

DSO SUMMARY

School	Assess Condition		Annual Condition Report (June 2019)		Congressional
	Q-Rating	FCI	Q-Rating	FCI	Q-Rating
Naples Community Superintendent's Office	Q-1	99	N/A	N/A	N/A

BUILDING SUMMARY

Building/School	Year Built	GSF	Type
Naples CSO Bldg 446	1998	2,115	PERM

⁴ This GSF represents DoDEA's allocation and NOT the total size of the building. DoDEA utilizes approximately 2% of the total facility.

I. INTRODUCTION

The Naples Community Superintendent's Office is part of Naval Support Activity Naples, Italy. This report provides a summary of findings for the physical condition assessment of the building at this campus. Building 446 is a partial-use facility. DoDEA utilizes approximately 2% of Building 446. The space utilized in Building 446 supports the Naples Community Superintendent's Office. The physical condition assessment includes a general description of typical building systems found and includes conditions present at the time of the site visit.

II. SCHOOL PHYSICAL DESCRIPTION

The summary below provides a physical description of the Naples Community Superintendent's Office. When multiple systems or materials are present, the predominant system or material observed during the facility condition assessment is shown.

- a. **STRUCTURAL/EXTERIOR ENCLOSURE:** The building exterior is stucco. Roof coverings are modified bitumen. Exterior doors are pre-finished aluminum with glazing. Window systems are pre-finished aluminum with double-glazing.
- b. **INTERIORS:** Floor finishes used include ceramic tile and carpet. Walls are painted hard surfaces. Ceilings are acoustical lay-in tiles.
- c. **MECHANICAL:** The Community Superintendent's Office facility has heating, which is provided by a central plant. The facility has air conditioning, which is provided by a central plant.
- d. **ELECTRICAL:** No electrical upgrades have been completed, and most wiring appears to be original. Lighting is typically lay-in fixtures with fluorescent lamps. Ground-fault circuit interrupter (GFCI) receptacles appear to be present in required locations. The Community Superintendent's Office does not have an intercom system. There is no security system, and security cameras are not present.
- e. **PLUMBING:** Plumbing fixtures and piping are original. Domestic hot water is provided by indirect water heaters.
- f. **SITE:** The Community Superintendent's Office has parking for approximately one privately owned vehicle.
- g. **LIFE SAFETY:** A fire safety inspection report was not available for review.

"Identification only"

III. OBSERVATIONS

The following observations were made: This was the initial BUILDER inventory for the Naples Community Superintendent's Office (CSO) Building 446. Exterior door security was not reported to be a problem. The stucco finish on the six-story exterior walls of Building 446 is severely deteriorated, with brittle stucco areas and peeling paint observed. Additionally, the roof was not accessible during the time of the assessment. The interior systems are overall in good condition. It appears outside air is being introduced into the HVAC system. The HVAC system supporting the space in Building 446 is supplied by the base, but the office spaces have a zoned system with thermostat controls to regulate occupied office space temperature. The Naples CSO utilizes Rooms 1, 2, 3, 4, and 4A in Building 446 and the facility is considered a partial-use facility. DoDEA utilizes approximately 2% of Building 446 (2,115 SF) while the Naval Support Activity Capodichino Agencies utilize approximately 98% of Building 446 (130,319 SF) for a total GSF value of 132,434 SF.

Building 446 is a Q-1 and was new at the time of the assessment.

IV. QUALITY / CONDITION RATINGS

Table 1 shows building-specific information to include Real Property Unique Identifier (RPUID), type of construction, year built, gross area, Facility Condition Index (FCI), and Q-Rating. Table 2 shows buildings that are classified as temporary (TEMP) or relocatable (RELO) and therefore, by definition, are not included in Quality/Condition calculations.

TABLE 1: QUALITY / CONDITION RATINGS								
Photo	Building	RPUID	Type	Year Built	GSF	Assessed		Plant Replacement Value ⁵
						FCI	Q-Rating	
	446	166024	PERM	1998	2,115	99	Q 1	—

⁵ The Plant Replacement Value is calculated according to the DoD Facility Pricing Guide

TABLE 2: TEMPORARY / RELOCATABLE BUILDINGS						
Photo	Building	Type	Year Built	GSF	Current Use	

No Buildings displayed...

Appendix A

Site Plan

"identification only"

Appendix B

Overview of Sustainment Management System (SMS) and
BUILDER™ Engineered Management System (EMS)

"identification only"

Overview of Sustainment Management System (SMS) and BUILDER™ Engineered Management System (EMS)

Sustainment Management System (SMS)

The Sustainment Management System (SMS) is a suite of web-based software applications developed by the United States Army Corps of Engineers - Engineer Research Development Center - Construction Engineering Research Laboratory (USACE-ERDC-CERL) to help facility engineers, technicians, and managers decide when, where, and how to best maintain the built environment. The SMS modules include BUILDER™ and ROOFER™ for assessing building conditions, PAVER™ for pavements, and RAILER™ for railroad infrastructure.

Because real property assets are so vast and diverse, a "knowledge-based" philosophy drives the SMS process. The process starts with the automated download of real property data, and then more detailed system inventory is modeled and/or collected which identifies components and their key life cycle attributes such as the age and material.

From this inventory, Condition Index (CI) measures for each component are predicted based on its expected stage in the life cycle. Objective and repeatable inspections can then be performed on various components to verify their condition with respect to the expected life cycle deterioration. The level of detail and frequency of these inspections are not fixed like other processes; they are dependent on knowledge of component criticality, the expected and measured condition and rate of deterioration, and remaining maintenance and service life. This "knowledge-based" inspection focuses attention to the most critical components at the time. In addition to these condition assessments, functionality assessments can be performed to evaluate user requirement changes, compliance and obsolescence issues. This provides a comprehensive picture of the overall performance of real property assets and their key components.

BUILDER Engineered Management System (EMS)

In September 2013, the Under Secretary of Defense, Frank Kendall, issued a memo indicating the Department of Defense requires a standardized process for facility condition assessments to ensure consistent and reliable data necessary for sound strategic investment decisions in managing the Department's built environment.

Establishing a DoD-wide facility condition assessment process will contribute to a more credible DoD asset management program and will support better buying power by allowing Department leadership to better target fiscal resources to those facilities most in need of investment. Further, adopting a standard process will help ensure that condition data will be audit-ready in accordance with the Under Secretary of Defense (Comptroller)'s "Financial Improvement and Readiness Guidance" issued in March 2013.

The facility condition assessment process used to generate this report is based on BUILDER Engineered Management System (EMS) Version 3. BUILDER EMS was developed by the Engineer Research and Development Center.

The facility condition assessment process addresses the requirements necessary for routine building facility management activities, including long range budgeting and sustainment/restoration/modernization (SRM) planning. This assessment approach provides an objective and generalized framework to help to identify problem areas that will require more investigation through detailed or specialized assessments. There may be times when detailed engineering assessments may be required to diagnose specific problems.

BUILDER is a software application for building asset life cycle management. The primary focus of BUILDER is work plan development. BUILDER stores real property building information and more detailed system inventory is modeled and/or collected which identifies building components and their key life cycle attributes such as the age, material and capacity. Inspections are then performed on the various components to

determine an objective and repeatable Condition Index (CI) measure, which relates the general physical health of the asset.

With information about condition and remaining service life, BUILDER guides the development of short- and long-range work plans based on sound investment strategies, prioritization criteria, and budget constraints. BUILDER consolidates a variety of building-related management issues into a single decision-support package.

The system gives functional managers and decision-makers instant access to building inventory, current building condition indices, and probabilities condition prediction models. It also employs a patented knowledge-based inspection scheduling process. BUILDER improves the allocation process and return of building life cycle investments by directing resources to the most condition critical components to avoid costly repair penalty costs, as well as, the most mission critical components to manage risks of failure.

BUILDER Facility Condition Assessment Process

Facility Condition Assessment (FCA) is one of the primary processes of a facility life cycle asset management program. The FCA process results in a better understanding of the physical condition and readiness of an organization's buildings along with the reliability of its systems and components. It also facilitates the identification of work candidates for facility SRM repair projects. It is a critical aspect of the shift towards a proactive versus reactive facility management strategy. Instead of keeping facilities operational by relying primarily on corrective repairs (after a system or component has failed due to significant loss of function), it focuses on condition-based repairs which can be planned prior to failure. A condition-based approach can result in higher performing facilities at lower life cycle costs.

Prior to an assessment, knowledge of the building systems and components present is necessary, since assessments are done against these components, not against the building as a whole. This information about the systems and components that make up a building is called the BUILDER Inventory. BUILDER has a vast library of predefined components which all assessors will select from, and the inventory collection process involves identifying the type, quantity, and year installed for all pertinent components. These components are also organized into systems and sub-systems according to the UNIFORMAT classification hierarchy. When a specific instance of a component is recorded, this is called a component-section in BUILDER, and represents a single component assembly or collection of like components to be managed as a single unit. The BUILDER facility condition assessment process directly supports the computation of a condition index for building component-sections, known as the Component-Section Condition Index (CSCI), which is the fundamental metric used in BUILDER. The CSCI is aggregated to compute a condition index metric at the system (SCI), building (BCI), and site/organizational level.

A condition-based facility repair strategy requires condition information be collected at a component level, and that this condition information relate to loss of component function. Every component of a building has a primary function that it performs. This function is the reason that the component was constructed or installed in the building. It may also serve a number of secondary or tertiary functions. For example, for a door component, the primary function is to provide safe entry/egress of authorized movements while limiting unwanted movements of people (security), or other objects (water or moisture). The secondary functions would relate to aesthetics and thermal and air control, among others.

The condition assessment process in BUILDER uses the Direct Rating method.

1. The **Direct Rating** method uses a single qualitative rating for each component based on condition observations. This also results in a condition index metric, which relates to the level of deterioration and the loss of function. This abbreviated Direct Rating approach is often better suited to initial baseline assessments where the components are inventoried, and data is initially loaded into BUILDER.

The following figure illustrates the Direct Rating criteria used in this assessment.

RATING	SRM NEEDS	RATING DEFINITION
Green (+)	Sustainment consisting of possible preventive maintenance (where applicable)	Entire component-section or component-section sample is free of observable or known distress.
Green	Sustainment consisting of possible preventive maintenance (where applicable) and minor repairs (corrective maintenance) to possibly few or some subcomponents.	No component-section or sample serviceability* or reliability* reduction. Some, but not all minor (non-critical) subcomponents may suffer from slight degradation or few major (critical) subcomponents may suffer from slight degradation.
Green (-)		Slight or no serviceability or reliability or reliability reduction overall to the component-section or sample. Some, but not all minor (non-critical) subcomponents may suffer from slight degradation or more than one major (critical) subcomponents may suffer from slight degradation.
Amber (+)	Sustainment or restoration to any of the following: Minor repairs to several sub-components; or Significant repair, rehabilitation or replacement of one or more subcomponents, but not enough to encompass the component-section as a whole; or Combinations thereof.	Component-section or sample serviceability or reliability is degraded, but adequate. A very few major (critical) subcomponents may suffer from moderate deterioration with perhaps a few minor (non-critical) subcomponents suffering from severe deterioration.
Amber		Component-section or sample serviceability or reliability is definitely impaired. Some, but not a majority of major (critical) subcomponents may suffer from moderate deterioration with perhaps many minor (non-critical) subcomponents suffering from severe deterioration.
Amber (-)		Component-section or sample has significant serviceability or reliability loss. Most subcomponents may suffer from moderate degradation or a few major (critical) subcomponents may suffer from severe degradation.
Red (+)	Sustainment or restoration required consisting of major repair, rehabilitation or replacement to the component-section as a whole.	Significant serviceability or reliability reduction in component-section or sample. A majority of subcomponents are severely degraded, and others may have varying degrees of degradation.
Red		Severe serviceability or reliability reduction to the component-section or sample such that it is barely able to perform. Most subcomponents are severely degraded.
Red (-)		Overall component-section degradation is total. Few, if any subcomponents are salvageable. Complete loss of component-section or sample serviceability.

Once the component-sections have been rated with a Direct Rating, BUILDER calculates the Component-Section Condition Index (CSCI) of the component-section. The next step in the process is to create a work plan, which will list the component-sections that need repair or replacement and the estimated cost of the repair or replacement.

To create a work plan, condition standards, policies and a policy sequence are created. The standards serve as thresholds for CSCI and remaining service life. Policies link standards to component-sections and policy sequences link standards and policies together.

The table below summarizes the DoDEA standards and how they are applied to the component-sections for this assessment.

Standard and Component-section Cross-Reference		
Standard	CI Threshold	Component-section
Amber +	80	D4010 FIRE ALARM AND DETECTION SYSTEMS
Amber	71	B3010 ROOF COVERINGS D1010 ELEVATORS AND LIFTS D2010 PLUMBING FIXTURES D3020 HEAT GENERATING SYSTEMS D3030 COOLING GENERATING SYSTEMS D3040 DISTRIBUTION SYSTEMS (A) D3050 TERMINAL & PACKAGE UNITS D3060 CONTROLS & INSTRUMENTATION D3090 OTHER HVAC SYSTEMS AND EQUIPMENT D4020 FIRE SUPP WATER SUPPLY / EQUIP D4030 STANDPIPE SYSTEMS D4040 SPRINKLERS D4050 FIRE PROTECTION SPECIALTIES D4090 OTHER FIRE PROTECTION SYSTEMS D5010 ELECTRICAL SERVICE & DISTRIBUTION D5020 LIGHTING & BRANCH WIRING D5030 COMMUNICATIONS & SECURITY D5090 OTHER ELECTRICAL SERVICES
Amber -	61	B2030 EXTERIOR DOORS C1020 INTERIOR DOORS C3010 WALL FINISHES C3020 FLOOR FINISHES C3030 CEILING FINISHES C3040 INT COATINGS / SPECIAL FINISHES D3010 ENERGY SUPPLY
Red +	50	B2010 EXTERIOR WALLS B2020 EXTERIOR WINDOWS C1030 SPECIALTIES D1020 WEIGHT HANDLING EQUIPMENT D1030 ESCALATORS AND MOVING WALKS D1090 OTHER CONVEYING SYSTEMS D2020 DOMESTIC WATER DISTRIBUTION D2030 SANITARY WASTE D2040 RAIN WATER DRAINAGE D2090 OTHER PLUMBING SYSTEMS D3070 SYSTEMS TESTING & BALANCING
Service Life	40	Paint

For this project, the following building components are not included in the BUILDER Inventory and are not evaluated during the assessment unless significant damage or deterioration was observed or reported.

- A1010 STANDARD FOUNDATIONS
- A1020 SPECIAL FOUNDATIONS
- A1030 SLAB ON GRADE
- A2010 BASEMENT EXCAVATION
- A2020 BASEMENT WALLS
- B1010 FLOOR CONSTRUCTION
- B1020 ROOF CONSTRUCTION
- B2010 EXTERIOR WALLS
- C1010 PARTITIONS
- C2010 STAIR CONSTRUCTION

Damage that is not visible or that is unknown will not be reflected in facility condition index calculations. It is anticipated that unknown damage or deterioration is more likely to be present in older facilities than more modern facilities.

In addition, some building components are concealed or inaccessible. In accordance with BUILDER guidelines, quantities for concealed and inaccessible components have been estimated and recorded in the BUILDER Inventory but have not been rated. When concealed or inaccessible components are encountered, life cycle data contained within BUILDER is used to predict renewal requirements, which are included in facility condition index calculations. Components that are often concealed or inaccessible include:

- D2020 DOMESTIC WATER PIPING
- D2030 SANITARY WASTE PIPING
- D3040 HVAC DISTRIBUTION
- D4010 FIRE ALARM DISTRIBUTION
- D5020 ELECTRICAL BRANCH WIRING

In addition to the building components noted above, if a building component is concealed or inaccessible, life cycle data contained within BUILDER is used to predict renewal requirements.

When a work plan is created, the CSCI of a component-section is compared to its associated standard. If the CSCI is less than or equal to the threshold in the standard, the remaining service life is evaluated. If the service life is less than the standard's remaining service life, BUILDER will add this section to the work plan and generate dollars to estimate a cost for the replacement.

If the CSCI is less than or equal to the threshold in the standard and the service life is greater than the standard's remaining service life, BUILDER will conduct a cost benefit analysis. The cost benefit analysis will determine whether the component-section should be repaired or left to expire at the end of its service life. When BUILDER determines a repair is the correct action, BUILDER will add this section to the work plan and generate dollars to estimate a cost for the repair.

When BUILDER determines taking no action is more cost effective, BUILDER will not add the component-section to the work plan. For example, if the CSCI for an external door component-section is 50 with a remaining service life of five years, BUILDER will compare the CSCI of 50 to the CI Threshold set by DoDEA and determine that 50 is less than the threshold of 61. BUILDER will compare the five years of remaining services life against the zero years of the threshold and determine a cost benefit analysis is required. The results of the cost benefit analysis will typically suggest to take no action and let the component-section run until the end of its service life before generating an item in the work plan.

A typical life cycle of a component-section is explained below.

Condition	Work Plan
CSCI > threshold	Work plan does not generate an item for the component-section
CSCI = threshold or just below it	Work plan will generate a repair item for the component-section

CSCI < threshold and the remaining service life > service life threshold	Work plan will remove the repair item for the component-section. It is too costly to repair so it is better to wait to replace it.
Remaining service life < service life threshold	Work plan will generate a replace item for the component-section

Facility Condition Assessment Data Analysis

In multiple building portfolios and especially with widespread geographic portfolios, it is important to know how building conditions compare. The Condition Index (CI) and Quality Ratings (Q-Ratings) are determined for each building assessed using guidelines shown below.

Condition Index (CI) – A measure of the constructed asset's condition at a specific point in time with respect to physical condition and ability to support the current occupant or mission. CI is calculated as the ratio of estimated cost of maintenance and repair requirements to Plant Replacement Value (PRV). Maintenance and repair requirements consist of that work necessary to ensure that a constructed asset is restored to a condition substantially equivalent to the originally intended and designed capacity, efficiency or capability. The formula for Condition Index is:

$$CI = 1 - \left(\frac{\text{Requirements}}{\text{PRV}} \right) \times 100$$

Q-Rating Bands – Bands allow OSD, Military Services, and Defense Agencies/Activities to group facilities by condition for the purposes of developing investment strategies.

TABLE 1: Q-RATING DESCRIPTIONS		
Rating Band	Calculated Rating (Condition Index)	General Description
Q-1	100 to 90	Facility new or well maintained (Good Condition)
Q-2	89 to 80	Facility is satisfactorily maintained (Fair Condition)
Q-3	79 to 60	Facility is under maintained (Poor Condition)
Q-4	59 to 0	Facility should be considered for replacement (Failing Condition)

Requirements – Sum of the work items from BUILDER.

Plant Replacement Value – Cost to design and construct a notional facility to current standards to replace an existing facility on the same site, (reference United Facilities Criteria UFC 3-701-01 23 May 2018, Change 3, 29 July 2019).

BUILDER Report Overview

Outlined below is a summary and description of the reports that are included.

Appendix C - Facility Summary Report – Provides a summation of FCA results. A Building Summary Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating. The purpose of this report is to provide a general overview of the building including key performance indicators. This report was generated using DoDEA's calculated Replacement Cost overwriting the data populated from real property records. This provides a more accurate Replacement Cost due to the inconsistencies with real property reconciliation between DoDEA and the Services. The DoD Facility Pricing Guide and DoDEA measurements for building square footage were used to calculate the Replacement Cost.

Appendix D - System Summary Report – Provides an overview of inspected systems and their condition index rating. A Building System Condition Index (SCI) By System Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating.

Appendix E - Work Items By Building – Provides a list of work items requiring repair or replacement of system/components, including budgets, for project planning purposes. A Work Plan Detail by Year Report is included for each building that is considered permanent or semi-permanent construction and receives a Q-Rating.

Appendix F - Remaining Service Life (RSL) Detail Report – Provides a detailed overview of systems/components, including descriptions, and their respective age, remaining service life and remaining paint life.

Appendix G - Direct Condition Rating Inspection By Section Report – Provides a summary of direct condition ratings for each component-section collected within each facility.

Appendix H - System Inventory Report – Provides a list of details for each component-section collected within each facility.

Appendix I - Fire Inspection Safety Report – This appendix is only applicable when a Fire Inspection Safety Report is provided at the time of the assessment for inclusion in the Facility Condition Assessment Report. The report provides a summary of the recent Fire Inspection to include any deficiencies.

Note: All reports are generated from the DoDEA BUILDER database. In the event line items within a report are compressed and difficult to read, this is a result of how BUILDER generates the report. It is our understanding that CERL is working to update the report format.

Summary of Terms

Acronyms	Description
BCI	Building Condition Index - Measures the condition of the building as a whole. The higher the BCI, the better.
BFI	Building Functionality Index - Measures the functionality of a building as a whole. The higher the BFI, the better.
BPI	Building Performance Index - Measures the overall performance of a building. The higher the BPI, the better.
EA	Each
ESC	Emergency Service Call
FCI	Facility Condition Index - The current maintenance, repair, and replacement deficiencies of the facility divided by the current replacement value of the facility, derives the FCI of a facility. The higher the FCI, the better.
GSF	Gross Square Foot
ISR	Installation Status Report - Measures installation condition against Army-wide standards.
LF	Linear Feet
MBH	Thousands of BTU per hour.
MDI	Mission Dependency Index - Measures how critical a facility is to the overall mission of its owner. The higher the MDI, the more critical.
PERM	Permanent
RELO	Relocatable
RPL	Remaining Paint Life - Displays the remaining paint life, in years, of a section.
RPUID	Real Property Unique Identifier - The unique identification number assigned to each asset.
RSL	Remaining Service Life - Displays the remaining service life, in years, of a section.
SCI	System Condition Index - Measures the condition of a system as a whole. The higher the SCI, the better.
SF	Square Foot
TEMP	Temporary
UM	Unit of Measure

Appendix C

Facility Summary Report

"identification only"

446* - Naples CSO Bldg 446*
Support Site - Naples CSO



YEAR BUILT:	1998
AREA (SF):	2,115
PLANT REPLACEMENT COST:	
SURVEY DATE:	January 2020
TOTAL DEFICIENCIES:	

BUILDER(TM) METRIC		SCORE
Facility Condition Index	FCI:	99

Appendix D

System Summary Report

"identification only"

DoDEA SYSTEM SUMMARY

Support Site

Complex	Building #	Building Name	A10	A20	B10	B20	B30	C10	C20	C30	D10	D20	D30	D40	D50	E10	E20	F10	F20	G10	G20	G30	G40	G90
Naples CSO	446*	Naples CSO Bldg 446*				90		94		95		85	83	100	98									

A10 - Foundations

A20 -Basement Construction

B10 - Superstructure

B20 - Exterior Enclosure

B30 - Roofing

C10 - Interior Construction

C20 - Stairs

C30 - Interior Finishes

D10 - Conveying

D20 - Plumbing

D30 - HVAC

D40 - Fire Protection

D50 - Electrical

E10 - Equipment

E20 - Furnishings

F10 - Special Construction

F20 - Selective Building Demo

G10 - Site Preparations

G20 - Site Improvements

G30 - Site Civil / Mech Utilities

G40 - Site Electrical Utilities

G50 - Other Site Construction

"identification only"

Appendix E

Work Items By Building

"identification only"



Work Items by Building Report



Support Site

Cost Book: Reference

446* - Naples CSO Bldg 446*

Naples CSO (HE5605)

Year	System	Component	Section Description	Qty (UM)	Activity	Project	Cost	Status	Score	Completion Date
-- Description										
2020	D20	PLUMBING								
	D2030	SANITARY WASTE		62 (EA)	Replace					0.00
	1998	D203002 VENT PIPE & FITTINGS General								
		-- Replace D2030 SANITARY WASTE 1998 D203002 VENT PIPE & FITTINGS General								

"Identification only"

Appendix F

Remaining Service Life (RSL) Detail Report

"identification only"

Support Site

446* - Naples CSO Bldg 446*

Naples CSO (HE5605)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1998 B201001 EXTERIOR CLOSURE Stone	22	50	
	B2010 EXTERIOR WALLS	1998 B201001 EXTERIOR CLOSURE Stucco	22	21	
	B2010 EXTERIOR WALLS	1998 B201007 EXTERIOR SOFFITS General	22	13	5
	B2010 EXTERIOR WALLS	1998 B201010 EXTERIOR JOINT SEALANT General	22	10	
	B2020 EXTERIOR WINDOWS	1998 B202001 WINDOWS Aluminum Windows	22	39	
	B2020 EXTERIOR WINDOWS	1998 B202002 STOREFRONTS General	22	10	
	B2030 EXTERIOR DOORS	1998 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress	22	10	4
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1998 C101001 FIXED PARTITIONS Wall - Concrete Block	22	50	Unknown
	C1010 PARTITIONS	1998 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	22	33	Unknown
	C1020 INTERIOR DOORS	1998 C102001 STANDARD INTERIOR DOORS Wood Door/Wood Frame	1	26	
	C1030 SPECIALTIES	1998 C103009 CABINETS Other	1	13	
	C1030 SPECIALTIES	1998 C103010 CASEWORK General	1	13	
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1998 C301004 TILE & TERRAZZO WALL FINISHES General	1	50	
	C3020 FLOOR FINISHES	1998 C302001 TILE FLOOR FINISHES Ceramic Tile	1	50	
	C3020 FLOOR FINISHES	1998 C302005 CARPETING General	1	4	
	C3030 CEILING FINISHES	1998 C303001 ACOUSTICAL CEILING TILES & PANELS General	1	46	
	C3030 CEILING FINISHES	1998 C303005 SUSPENSION SYSTEMS General	1	13	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1998 D201001 WATERCLOSETS General	1	13	
	D2010 PLUMBING FIXTURES	1998 D201004 SINKS General	1	13	
	D2010 PLUMBING FIXTURES	1998 D201004 SINKS Stainless	1	13	
	D2020 DOMESTIC WATER DISTRIBUTION	1998 D202001 PIPES & FITTINGS General	22	28	
	D2030 SANITARY WASTE	1998 D203001 WASTE PIPE & FITTINGS General	22	28	
	D2030 SANITARY WASTE	1998 D203002 VENT PIPE & FITTINGS General	22	0	
D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1998 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	22	18	
	D3040 DISTRIBUTION SYSTEMS	1998 D304007 EXHAUST SYSTEMS Fan System, Residential Exhaust	1	26	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION	1998 D401001 FIRE ALARM DISTRIBUTION Other	1	19	
	D4040 SPRINKLERS	1998 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	1	74	
D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	1998 D502001 BRANCH WIRING General	1	59	
	D5020 LIGHTING & BRANCH WIRING	1998 D502002 LIGHTING EQUIPMENT Exit Lighting	1	13	



Support Site

446* - Naples CSO Bldg 446*

Naples CSO (HE5605)

System	Component	Section Description	Age (yrs)	RSL (yrs)	RPL (yrs)
	D5020 LIGHTING & BRANCH WIRING	1998 D502002 LIGHTING EQUIPMENT Exterior Lighting	22	10	
	D5020 LIGHTING & BRANCH WIRING	1998 D502002 LIGHTING EQUIPMENT General	1	13	
	D5090 OTHER ELECTRICAL	1998 D509002 EMERGENCY LIGHTING & POWER General	1	19	

"Identification only"

Appendix G

Direct Condition Rating Inspection By Section Report

"identification only"



Direct Condition Rating Inspection Report by Section



Support Site

446* - Naples CSO Bldg 446*

Naples CSO (HE5605)

Section Description	System	Component	Quantity (UM)
1998 B201001 EXTERIOR CLOSURE Stone	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	300 (SF)
Last Inspection Date: 14-Jan-2020 Condition Rating: G Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments: The exterior stone wainscot at walls and columns, is generally in good condition. However, there are some damaged areas of trim.			
1998 B201001 EXTERIOR CLOSURE Stucco	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	500 (SF)
Last Inspection Date: 14-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1998 B201007 EXTERIOR SOFFITS General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	800 (SF)
Last Inspection Date: 14-Jan-2020 Condition Rating: G Used Sampling? No Inspector: [REDACTED] Paint Rating: G Inspection Source: Inspection Inspection Comments:			
1998 B201010 EXTERIOR JOINT SEALANT General	B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	250 (LF)
Last Inspection Date: 14-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1998 B202001 WINDOWS Aluminum Windows	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	6 (EA)
Last Inspection Date: 14-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1998 B202002 STOREFRONTS General	B20 EXTERIOR ENCLOSURE	B2020 EXTERIOR WINDOWS	96 (SF)
Last Inspection Date: 14-Jan-2020 Condition Rating: G- Used Sampling? No Inspector: [REDACTED] Inspection Source: Inspection Inspection Comments:			
1998 B203090 OTHER EXTERIOR SPECIALTY DOORS	B20 EXTERIOR ENCLOSURE	B2030 EXTERIOR DOORS	4 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

446* - Naples CSO Bldg 446*

Naples CSO (HE5605)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 14-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G- Paint Rating: G-	Used Sampling? No Inspection Source: Inspection	
1998 C101001 FIXED PARTITIONS Wall - Concrete Block	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	105 (SF)
Last Inspection Date: 14-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G Paint Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 C101001 FIXED PARTITIONS Wall - Drywall w/Stud	C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	2,200 (SF)
Last Inspection Date: 14-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G Paint Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 C102001 STANDARD INTERIOR DOORS Wood	C10 INTERIOR CONSTRUCTION	C1020 INTERIOR DOORS	2 (EA)
Last Inspection Date: 14-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 C103009 CABINETS Other	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	15 (LF)
Last Inspection Date: 14-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 C103010 CASEWORK General	C10 INTERIOR CONSTRUCTION	C1030 SPECIALTIES	6 (LF)
Last Inspection Date: 14-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 C301004 TILE & TERRAZZO WALL FINISHES General	C30 INTERIOR FINISHES	C3010 WALL FINISHES	190 (SF)
Last Inspection Date: 14-Jan-2020 Inspector: Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	



Direct Condition Rating Inspection Report by Section



Support Site

446* - Naples CSO Bldg 446*

Naples CSO (HE5605)

Section Description	System	Component	Quantity (UM)
1998 C302001 TILE FLOOR FINISHES Ceramic Tile	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	150 (SF)
Last Inspection Date: 14-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 C302005 CARPETING General	C30 INTERIOR FINISHES	C3020 FLOOR FINISHES	1,965 (SF)
Last Inspection Date: 14-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 C303001 ACOUSTICAL CEILING TILES & PANELS	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	2,115 (SF)
Last Inspection Date: 14-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 C303005 SUSPENSION SYSTEMS General	C30 INTERIOR FINISHES	C3030 CEILING FINISHES	2,115 (SF)
Last Inspection Date: 14-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 D201001 WATERCLOSETS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 14-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 D201004 SINKS General	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)
Last Inspection Date: 14-Jan-2020 Inspector: [REDACTED] Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 D201004 SINKS Stainless	D20 PLUMBING	D2010 PLUMBING FIXTURES	1 (EA)



Direct Condition Rating Inspection Report by Section



Support Site

446* - Naples CSO Bldg 446*

Naples CSO (HE5605)

Section Description	System	Component	Quantity (UM)
Last Inspection Date: 14-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 D202001 PIPES & FITTINGS General	D20 PLUMBING	D2020 DOMESTIC WATER DISTRIBUTION	506 (LF)
Last Inspection Date: 01-Jan-1998 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1998 D203001 WASTE PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	253 (LF)
Last Inspection Date: 01-Jan-1998 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1998 D203002 VENT PIPE & FITTINGS General	D20 PLUMBING	D2030 SANITARY WASTE	62 (EA)
Last Inspection Date: 01-Jan-1998 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1998 D304001 AIR DISTRIBUTION, HEATING & COOLING	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	394 (LF)
Last Inspection Date: 01-Jan-1998 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	
1998 D304007 EXHAUST SYSTEMS Fan System, Residential	D30 HVAC	D3040 DISTRIBUTION SYSTEMS	2 (EA)
Last Inspection Date: 14-Jan-2020 Inspector: XXXXXXXXXX Inspection Comments:	Condition Rating: G	Used Sampling? No Inspection Source: Inspection	
1998 D401001 FIRE ALARM DISTRIBUTION Other	D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SY\$	2,115 (SF)
Last Inspection Date: 01-Jan-2019 Inspector: Inspection Comments: Original Inspection	Condition Rating: G+	Used Sampling? No Inspection Source: InstallDate	



Direct Condition Rating Inspection Report by Section



Support Site

446* - Naples CSO Bldg 446*

Naples CSO (HE5605)

Section Description	System	Component	Quantity (UM)
1998 D404001 SPRINKLERS AND RELEASING DEVICES Wet	D40 FIRE PROTECTION	D4040 SPRINKLERS	11 (SF)
Last Inspection Date: 01-Jan-2019	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
1998 D502001 BRANCH WIRING General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	2,115 (SF)
Last Inspection Date: 01-Jan-2019	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			
1998 D502002 LIGHTING EQUIPMENT Exit Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	3 (EA)
Last Inspection Date: 14-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1998 D502002 LIGHTING EQUIPMENT Exterior Lighting	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	1 (EA)
Last Inspection Date: 14-Jan-2020	Condition Rating: G-	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1998 D502002 LIGHTING EQUIPMENT General	D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	2,115 (SF)
Last Inspection Date: 14-Jan-2020	Condition Rating: G	Used Sampling? No	Inspection Source: Inspection
Inspector: [REDACTED]			
Inspection Comments:			
1998 D509002 EMERGENCY LIGHTING & POWER General	D50 ELECTRICAL	D5090 OTHER ELECTRICAL SERVICES	2,115 (SF)
Last Inspection Date: 01-Jan-2019	Condition Rating: G+	Used Sampling? No	Inspection Source: InstallDate
Inspector:			
Inspection Comments: Original Inspection			

Appendix H

System Inventory Report

"identification only"



System Inventory Report



Support Site

446* - Naples CSO Bldg 446*

Naples CSO (HE5605)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
B20 EXTERIOR ENCLOSURE	B2010 EXTERIOR WALLS	1998 B201001 EXTERIOR CLOSURE Stone	300 (SF)	1998	
	B2010 EXTERIOR WALLS	1998 B201001 EXTERIOR CLOSURE Stucco	500 (SF)	1998	
	B2010 EXTERIOR WALLS	1998 B201007 EXTERIOR SOFFITS General	800 (SF)	1998	1998
	B2010 EXTERIOR WALLS	1998 B201010 EXTERIOR JOINT SEALANT General	250 (LF)	1998	
	B2020 EXTERIOR WINDOWS	1998 B202001 WINDOWS Aluminum Windows	6 (EA)	1998	
	B2020 EXTERIOR WINDOWS	1998 B202002 STOREFRONTS General	96 (SF)	1998	
	B2030 EXTERIOR DOORS	1998 B203090 OTHER EXTERIOR SPECIALTY DOORS Emergency Egress Door	4 (EA)	1998	1998
C10 INTERIOR CONSTRUCTION	C1010 PARTITIONS	1998 C101001 FIXED PARTITIONS Wall - Concrete Block	105 (SF)	1998	2019
	C1010 PARTITIONS	1998 C101001 FIXED PARTITIONS Wall - Drywall w/Stud Framing	2,200 (SF)	1998	2019
	C1020 INTERIOR DOORS	1998 C102001 STANDARD INTERIOR DOORS Wood Door/Wood Frame	2 (EA)	2019	
	C1030 SPECIALTIES	1998 C103003 CABINETS Other	15 (LF)	2019	
	C1030 SPECIALTIES	1998 C103013 CASEWORK General	6 (LF)	2019	
C30 INTERIOR FINISHES	C3010 WALL FINISHES	1998 C301004 TILE & TERRAZZO WALL FINISHES General	190 (SF)	2019	
	C3020 FLOOR FINISHES	1998 C302001 TILE FLOOR FINISHES Ceramic Tile	150 (SF)	2019	
	C3020 FLOOR FINISHES	1998 C302005 CARPETING General	1,965 (SF)	2019	
	C3030 CEILING FINISHES	1998 C303001 ACOUSTICAL CEILING TILES & PANELS General	2,115 (SF)	2019	
	C3030 CEILING FINISHES	1998 C303005 SUSPENSION SYSTEMS General	2,115 (SF)	2019	
D20 PLUMBING	D2010 PLUMBING FIXTURES	1998 D201001 WATERCLOSETS General	1 (EA)	2019	
	D2010 PLUMBING FIXTURES	1998 D201004 SINKS General	1 (EA)	2019	
	D2010 PLUMBING FIXTURES	1998 D201004 SINKS Stainless	1 (EA)	2019	
	D2020 DOMESTIC WATER DISTRIBUTION	1998 D202001 PIPES & FITTINGS General	506 (LF)	1998	
	D2030 SANITARY WASTE	1998 D203001 WASTE PIPE & FITTINGS General	253 (LF)	1998	
	D2030 SANITARY WASTE	1998 D203002 VENT PIPE & FITTINGS General	62 (EA)	1998	
D30 HVAC	D3040 DISTRIBUTION SYSTEMS	1998 D304001 AIR DISTRIBUTION, HEATING & COOLING Ductwork	394 (LF)	1998	
	D3040 DISTRIBUTION SYSTEMS	1998 D304007 EXHAUST SYSTEMS Fan System, Residential Exhaust	2 (EA)	2019	
D40 FIRE PROTECTION	D4010 FIRE ALARM AND DETECTION SYSTEMS	1998 D401001 FIRE ALARM DISTRIBUTION Other	2,115 (SF)	2019	
	D4040 SPRINKLERS	1998 D404001 SPRINKLERS AND RELEASING DEVICES Wet Pipe Systems	11 (SF)	2019	
D50 ELECTRICAL	D5020 LIGHTING & BRANCH WIRING	1998 D502001 BRANCH WIRING General	2,115 (SF)	2019	



System Inventory Report



Support Site

446* - Naples CSO Bldg 446*

Naples CSO (HE5605)

System	Component	Section Description	Quantity (UM)	Yr. Installed	Yr Painted
	D5020 LIGHTING & BRANCH WIRING	1998 D502002 LIGHTING EQUIPMENT Exit Lighting	3 (EA)	2019	
	D5020 LIGHTING & BRANCH WIRING	1998 D502002 LIGHTING EQUIPMENT Exterior Lighting	1 (EA)	1998	
	D5020 LIGHTING & BRANCH WIRING	1998 D502002 LIGHTING EQUIPMENT General	2,115 (SF)	2019	
	D5090 OTHER ELECTRICAL SERVICES	1998 D509002 EMERGENCY LIGHTING & POWER General	2,115 (SF)	2019	

"Identification only"