I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged I have read and understand the above and acknowledge receipt of an estimate



Terms. Cash unless arrangements are made prior to authorization. Vehicles left after repair is completed may be subjected to a \$85,00 per day storage charge

## All America

846 Harri San Francis (415) 9

ALL AMERICAN AUTOMOTIVE 846 HARRISON STREET SAN FRANCISCO CA 94107 415-957-1170

8627

6:12 PM

507.50

Terminal ID: 01557188 7/18/17 VISA CREDIT - INSERT

AID: A000000031010 ACCT #: \*\*\*\*\*\*\*\*\*\*9758

CREDIT SALE

THUOMA

UID: 719913590618 REF #: 2233 BATCH #: 194 AUTH #: 78289D

> \$2956.76 **APPROVED**

TC - 94784E281F4F8778 CUSTOMER COPY

## **Paras Apostolopoulos**

823 Kansas St

(415) 425-0517

San Francisco, CA 94105

VIN: WV3AB47004H001830

Engine: V6 2.8L, 2792cc, DOHC, GAS, FI

2003 Volkswagen EuroVan MV

Trans:

Unit#

License #

Odom: 29929

Color: White

Mfg. Date:

	olems Requ	ests for Service	Services Performed	Hrs	Qty		14140	
stomer stat	tes that: smog ins	pection			17	g into Mai		
Labor Serv	vice - California Em	ission Inspection	ВН	1.00		130.00	-78.30	51.70
New	SSC	California	Emission Certificate		1.00	8.25		8.2
engine per noted brok P1151 for	rformance test. Sca re EVAP line to pur	n fuel managemer ge valve under veh code P1476 Leak	or light on perform strategy based it management system. Inspection picle causing vehicle to have code detection pump malfunction. Replace	4.50		145.00		652.50
New	GASOLINE	Gasoline			1.00	30.00 13	29 64	30.0
New	7D0201995G	Vent Tub			1.00	88.80	- 1001	88.8
New	B7080-169083	Purge Va	-		1.00	58.98		58.9
New	7D0906271A		ection Pump		1.00	347.36	/	347.3
New	7D0906515		ent Solinoid		1.00	182.00	(	182.0
stomer stat	tes that: regular se	rvice needed				X Market		
* change e		enance service		1.50		145.00		217.5
* adjust al * check ou * check tire * service b	oil filter r fluid leaks Il fluids Itside bulbs es/belts/hoses							
* check for * adjust al * check ou * check tire * service b * full safety	oil filter r fluid leaks Il fluids Itside bulbs es/belts/hoses pattery	1				145.00		0,0
* check for * adjust al * check ou * check tire * service b * full safety	oil filter r fluid leaks Il fluids Itside bulbs es/belts/hoses pattery y Inspection BH		ild washer fluid		1.00	145.00 6.69		
* check for * adjust al * check ou * check tire * service b * full safety Labor Serv	oil filter r fluid leaks Il fluids Itside bulbs es/belts/hoses pattery y Inspection BH vice - Parts Sold BI	Windshei	ild washer fluid r - Mann+Hummel		1.00			6.6
* check for * adjust al * check ou * check tire * service b * full safety Labor Service	oil filter r fluid leaks Il fluids Itside bulbs es/belts/hoses pattery y Inspection BH vice - Parts Sold BI WASHER FLUID	Windshei Fuel Filte				6.69		6.6 26.4
* check for * adjust al * check ou * check tire * service b * full safety Labor Service New New	oil filter r fluid leaks Il fluids Itside bulbs es/belts/hoses pattery y Inspection BH vice - Parts Sold BI WASHER FLUID WK8307	Windshei Fuel Filte Cabin Air	r - Mann+Hummel		1.00	6.69 26.40		6.6 26.4 29.5
* check for * adjust al * check ou * check tire * service b * full safety Labor Serv New New New	oil filter r fluid leaks Il fluids Itside bulbs es/belts/hoses pattery y Inspection BH vice - Parts Sold BI WASHER FLUID WK8307 CU1738	Windshei Fuel Filte Cabin Air Oil Filter	r - Mann+Hummel · Filter - Mann+Hummel		1.00 1.00	6.69 26.40 29.53		6.6 26.4 29.5 18.5
* check for * adjust al * check ou * check tire * service b * full safety Labor Service New New New New New New New Ne	oil filter r fluid leaks Il fluids Itside bulbs es/belts/hoses pattery y Inspection BH vice - Parts Sold BI WASHER FLUID WK8307 CU1738 HU7197X	Windshei Fuel Filte Cabin Air Oil Filter Motor Oil	r - Mann+Hummel : Filter - Mann+Hummel - Mann+Hummel		1.00 1.00 1.00	6.69 26.40 29.53 18.56		0.0 6.6 26.4 29.5 18.5 58.2
* check for * adjust al * check ou * check tire * service b * full safety Labor Service New New New New New New New Ne	ili filter r fluid leaks Il fluids Itside buibs es/belts/hoses eattery y inspection BH vice - Parts Sold BI WASHER FLUID WK8307 CU1738 HU7197X 31100-76949  te that: vehicle ner vice - Rear brake la ion material * check	Windshei Fuel Filte Cabin Air Oil Filter Motor Oil eds rear brakes bor * remove c drum/rotor * t	r - Mann+Hummel Filter - Mann+Hummel - Mann+Hummel Synthoil 5W-40 - 5 Ltr wheel assy * inspect hydraulics * est drive BH	1.50	1.00 1.00 1.00 1.00	6.69 26.40 29.53 18.56 58.20		6.6 26.4 29.5 18.5 58.2
* check for * adjust al * check ou * check tire * service b * full safety Labor Service New New New New New New New Labor Service Labor Service New Labor Service New Labor Service New Frection no	ili filter r fluid leaks Il fluids Itside bulbs es/belts/hoses pattery y inspection BH vice - Parts Sold BI WASHER FLUID WK8307 CU1738 HU7197X 31100-76949  te that: vehicle new vice - Rear brake lation material * check BC	Windshei Fuel Filte Cabin Air Oil Filter Motor Oil eds rear brakes bor * remove c drum/rotor * t Beeryma	r - Mann+Hummel Filter - Mann+Hummel - Mann+Hummel Synthoil 5W-40 - 5 Ltr  wheel assy * inspect hydraulics * est drive BH n solvent cleaner	1,50	1.00 1.00 1.00 1.00	6.69 26.40 29.53 18.56 58.20 145.00 8.67		6.6 26.4 29.5 18.5 58.2 217.5
* check for * adjust al * check ou * check tire * service b * full safety Labor Service New New New New New New Labor Service New Labor Service New New New New New New New Ne	ili filter r fluid leaks Il fluids Itside bulbs es/belts/hoses pattery y inspection BH vice - Parts Sold BI WASHER FLUID WK8307 CU1738 HU7197X 31100-76949  te that: vehicle new vice - Rear brake la idon material * check BC N1010-323500	Windshei Fuel Filte Cabin Air Oil Filter Motor Oil eds rear brakes bor * remove c drum/rotor * t Beeryma Brake Pa	r - Mann+Hummel Filter - Mann+Hummel - Mann+Hummel Synthoil 5W-40 - 5 Ltr  wheel assy * inspect hydraulics * est drive BH n solvent cleaner d Set-Rear - With Shims	1.50	1.00 1.00 1.00 1.00 1.00	6.69 26.40 29.53 18.56 58.20 145.00 8.67 110.65		6.6 26.4 29.5 18.5 58.2 217.5
* check for * adjust al * check ou * check tire * service b * full safety Labor Service New New New New New New New Labor Service Labor Service New Labor Service New Labor Service New Frection no	ili filter r fluid leaks Il fluids Itside bulbs es/belts/hoses pattery y inspection BH vice - Parts Sold BI WASHER FLUID WK8307 CU1738 HU7197X 31100-76949  te that: vehicle new vice - Rear brake lation material * check BC	Windshei Fuel Filte Cabin Air Oil Filter Motor Oil eds rear brakes bor * remove c drum/rotor * t Beeryma	r - Mann+Hummel Filter - Mann+Hummel - Mann+Hummel Synthoil 5W-40 - 5 Ltr  wheel assy * inspect hydraulics * est drive BH n solvent cleaner d Set-Rear - With Shims	1.50	1.00 1.00 1.00 1.00	6.69 26.40 29.53 18.56 58.20 145.00 8.67		6.6 26.4 29.5 18.5 58.2 217.5 8.6 110.6
* check for * adjust al * check ou * check tire * service b * full safety Labor Serv New	ili filter r fluid leaks Il fluids Itside bulbs es/belts/hoses eattery y inspection BH vice - Parts Sold BI WASHER FLUID WK8307 CU1738 HU7197X 31100-76949  te that: vehicle new vice - Rear brake lation material * check BC N1010-323500 N1000-125656 vice - Brake fluid se s with required fluid	Windshei Fuel Filte Cabin Air Oil Filter Motor Oil eds rear brakes bor * remove c drum/rotor * t Beeryma Brake Pa Brake Dis rvice * drain maste	r - Mann+Hummel Filter - Mann+Hummel - Mann+Hummel Synthoil 5W-40 - 5 Ltr  wheel assy * inspect hydraulics * est drive BH n solvent cleaner d Set-Rear - With Shims sc-Rear er cylinder & clean reservoir * flush all	1.50	1.00 1.00 1.00 1.00 1.00	6.69 26.40 29.53 18.56 58.20 145.00 8.67 110.65		6.6 26.4 29.5 18.5

3.50

145.00

Labor Service - install back up camera BH