Government College of Engineering, Amravata

(An Autonomous Institute of Government of Maharashtra)

CT-2 Sub- MEU504 (Metrology& measurement system)

Max Marks- 13

Solve any three (Each question carry 5 mark)

A1) State different gauges used for measurement of high & low pressure. Explain one high pressure & low pressure gauge. (5)

(Q2) A) A tensile strain of 0.001 has been applied to a strain gauge having a gauge factor of 2. The gauge resistance & other three resistances comprising the limbs of a Wheatstone bridge circuit have an initial resistance of 120 Ω . Find i) change in the value of variable resistance R2 to rebalance the null type bridge, ii) output voltage of a voltage sensitive bridge if the voltmeter resistance is very high & bridge supply voltage is 6V. (2)

B) Explain how dummy gauges are for temperature compensation with neat sketch. (3)

93) A) Draw a neat sketch of pressure type thermometer vihich converts temperature into pressure. Draw the generalized block diagram for it. (2)

B) Explain any three methods of correction for interfering and modifying inputs with neat sketch. (3)

Q4) A) Define the following i) accuracy & precision ii) dead time & dead zone iii) hysteresis & threshold. (3)

B) State difference between ballast circuit & Wheatstone bri lge circuit with diagram. (2)