Setup sheet: sheet

Job

Project	sheet
Machine	Example X rotary
Setups	2
Operations	4
Tools used	2
Programmed time	1:17

Setup: Setup 1

Part	models/cube.stl
Stock	cylinder, diameter 20 mm, length 14 mm, from X -7 mm
Stock material	oak
Work offset	G54, work zero at model X 0 mm on the rotary axis
Part offset	part moved 0 mm along the rotary axis from where its placement puts it
Held at the start	none
Held at the end	none
Tabs	none

Setup: Flip / side 2

Part	models/cube.stl
Stock	cylinder, diameter 20 mm, length 14 mm, from X -7 mm
Stock material	oak
Work offset	G54, work zero at model X 0 mm on the rotary axis
Part offset	part moved 0 mm along the rotary axis from where its placement puts it
Held at the start	none
Held at the end	none
Tabs	none

Tools

Tool	Name	Type	Dia mm	Flutes	Flute mm	Overall mm	Shank mm	Used in
T1	4 mm ball	ball end	4	2	10	40	4	Setup 1, Flip / side 2
T2	6 mm ball	ball end	6	2	10	40	6	Setup 1

Operations

No	Operation	Strategy	Setup	Tool	Spindle rpm	Speed from	Tolerance	Time
1	Finish A	Helical finishing	Setup 1	T1 4 mm ball	10000	tool data: oak	0.01 mm	0:20
2	Finish B	Helical finishing	Setup 1	T2 6 mm ball	10000	tool data: oak	0.01 mm	0:20
3	Touch up A	Helical finishing	Setup 1	T1 4 mm ball	10000	tool data: oak	0.01 mm	0:18
4	Side two	Helical finishing	Flip / side 2	T1 4 mm ball	10000	tool data: oak	0.01 mm	0:20

Notes

Time is the sum of the toolpath's move durations at their programmed feeds. It leaves out acceleration, tool changes and fixturing, and is not the simulated estimate. Generated G-code must be verified by the user before it is run on a machine. OpenChuckCAM does not guarantee that a program is safe or correct for any machine, tool or setup.

Traceability

Generated	2026-10-21T09:30:05Z
Project last saved	2026-10-21T09:12:00Z
Software version	0.0.0
Project fingerprint	blake3:abababababababababababababababababababababababababababababababab
Version control	not tracked