Setup sheet: sheet

Job

Project	sheet
Machine	Example X rotary
Setups	2
Operations	4
Tools used	2
Programmed time	1:17

Setup: Setup 1

Part	models/cube.stl
Stock	cylinder, diameter 20 mm, length 14 mm, from X -7 mm
Stock material	oak
Work offset	G54, work zero at model X 0 mm on the rotary axis
Part offset	0 mm along the rotary axis from the machine's reference point

Setup: Flip / side 2

Part	models/cube.stl
Stock	cylinder, diameter 20 mm, length 14 mm, from X -7 mm
Stock material	oak
Work offset	G54, work zero at model X 0 mm on the rotary axis
Part offset	0 mm along the rotary axis from the machine's reference point

Tools

Tool	Name	Type	Dia mm	Flutes	Flute mm	Overall mm	Shank mm	Used in
T1	4 mm ball	ball end	4	2	10	40	4	Setup 1, Flip / side 2
T2	6 mm ball	ball end	6	2	10	40	6	Setup 1

Operations

No	Operation	Strategy	Setup	Tool	Spindle rpm	Speed from	Tolerance	Time
1	Finish A	helical_finishing	Setup 1	T1 4 mm ball	10000	tool data: oak	0.01 mm	0:20
2	Finish B	helical_finishing	Setup 1	T2 6 mm ball	10000	tool data: oak	0.01 mm	0:20
3	Touch up A	helical_finishing	Setup 1	T1 4 mm ball	10000	tool data: oak	0.01 mm	0:18
4	Side two	helical_finishing	Flip / side 2	T1 4 mm ball	10000	tool data: oak	0.01 mm	0:20

Notes

Time is the sum of the toolpath's move durations at their programmed feeds. It leaves out acceleration, tool changes and fixturing, and is not the simulated estimate. Generated G-code must be verified by the user before it is run on a machine. OpenChuckCAM does not guarantee that a program is safe or correct for any machine, tool or setup.

Traceability

Generated	2026-10-21T09:30:05Z
Project last saved	2026-10-21T09:12:00Z
Software version	0.0.0
Project fingerprint	blake3:abababababababababababababababababababababababababababababababab
Version control	not tracked