# Setup sheet: sheet

## Job

| | |
|---|---|
| Project | sheet |
| Machine | Example X rotary |
| Setups | 2 |
| Operations | 4 |
| Tools used | 2 |
| Programmed time | 1:14 |

## Setup: Setup 1

| | |
|---|---|
| Part | models/cube.stl |
| Stock | cylinder, diameter 20 mm, length 14 mm, from X -7 mm |
| Stock material | oak |
| Work offset | G54, work zero at model X 0 mm on the rotary axis |
| Part offset | 0 mm along the rotary axis from the machine's reference point |

## Setup: Flip / side 2

| | |
|---|---|
| Part | models/cube.stl |
| Stock | cylinder, diameter 20 mm, length 14 mm, from X -7 mm |
| Stock material | oak |
| Work offset | G54, work zero at model X 0 mm on the rotary axis |
| Part offset | 0 mm along the rotary axis from the machine's reference point |

## Tools

| Tool | Name | Type | Dia mm | Flutes | Flute mm | Overall mm | Shank mm | Used in |
|---|---|---|---|---|---|---|---|---|
| T1 | 4 mm ball | ball end | 4 | 2 | 10 | 40 | 4 | Setup 1, Flip / side 2 |
| T2 | 6 mm ball | ball end | 6 | 2 | 10 | 40 | 6 | Setup 1 |

## Operations

| No | Operation | Strategy | Setup | Tool | Spindle rpm | Time |
|---|---|---|---|---|---|---|
| 1 | Finish A | helical_finishing | Setup 1 | T1 4 mm ball | 10000 | 0:20 |
| 2 | Finish B | helical_finishing | Setup 1 | T2 6 mm ball | 10000 | 0:18 |
| 3 | Touch up A | helical_finishing | Setup 1 | T1 4 mm ball | 10000 | 0:18 |
| 4 | Side two | helical_finishing | Flip / side 2 | T1 4 mm ball | 10000 | 0:20 |

## Notes

Time is the sum of the toolpath's move durations at their programmed feeds. It leaves out acceleration, tool changes and fixturing, and is not the simulated estimate. Generated G-code must be verified by the user before it is run on a machine. OpenChuckCAM does not guarantee that a program is safe or correct for any machine, tool or setup.