COLUMBUS, OHIO AL-5958 (FAA) 23166 WAAS 5500 Rwy Idg RNAV (GPS) RWY 4 APP CRS CH 90505 TDŻE 904 037° BOLTON FLD (TZR) Apt Elev 904 W04A RNP APCH. MISSED APPROACH: V MALSR Climb to 3000 direct For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above OYILU and left turn 54°C. For inop ALS, increase LNÁV/VNAV all Cats visibility to 11/4 SM and LNAV on track 294° to Cats C/D visibility to 1% SM. MECAN and hold. AWOS-3PT COLUMBUS APP CON BOLTON TOWER * GND CON 135.925 134.0 279.6 128.1 (CTAF) (121.8 2049 A 4 NM **■** 269° 089° **MECAN** '''''29_{4°1,} OYILU ۸¹⁷⁴⁸ <u>∧</u>1748 RW04 A1317 SARW04 25 Ny (FAF) Procedure NA for JÖXÖK 3100 arrivals at SHIRT on V5 southwest bound. \bigcirc (IF/IAF) WATIG 2700 NOP" 904 904 TDZE (IAF) HOLD 6000 SHIRT VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 25). 3000 OYILU MECAN 4 NM Holding Pattern 294° **JOXOK** WATIG *LNAV only 2700 217° 6000 1027 * 1.4 NM to 037° 2700 037° **RW04** 2700 RW04 GP 3.00° TCH 39 6.6 NM -4 NM CATEGORY Α D LPV DA 1163-1/2 259 (300-1/2) LNAV/ DA 1325-1 421 (500-1) VNAV 1360-78 1360-1 1360-1/2 456 (500-1/2) LNAV MDA 456 (500-1) 456 (500-78) REIL Rwy 22 🗓 1360-1 1380-1 1500-2

COLUMBUS, OHIO Orig-B 13SEP18

456 (500-1)

476 (500-1)

C CIRCLING

BOLTON FLD (TZR) RNAV (GPS) RWY 4

MIRL Rwy 4-22 (

EC-2, 13 JUL 2023 to 10 AUG 2023

596 (600-2)

1380-11/2

476 (500-11/2)