INSPECTION REPORT

LOLER Inspection

RTB Roofing Ltd · Studley Rd, London, SW4 6RZ

LOLER Inspection	Complete
Site	Rear elevation, scaffold lift 3
Inspected By	Rear elevation, scaffold lift 3
Conducted On	04 Nov 2026
Make & Model	Rear elevation, scaffold lift 3
Equipment Description	Rear elevation, scaffold lift 3
Serial Number / Identification	HST-0042

LOLER Inspection

RTB Roofing Ltd · Studley Rd, London, SW4 6RZ

LOLER Inspection

Regulation 3: Application

Is the equipment suitable for the task?	**Yes**

How often is the equipment used?

Rear elevation, scaffold lift 3

What is the nature and characteristics of the load

Slates slipped near the valley; battens sound. Lead flashing to the chimney needs re-dressing.

Is access to the equipment safe and suitable?	**No**

Regulation 4: Strength & Stability

Does the equipment have adequate strength for the proposed use?	**Yes**
Is the equipment of adequate stability for the job?	**Yes**
Are measures in place to resist overturning?	**Yes**
Are lifting points on loads of suitable strength?	**No**

Regulation 9: Thorough Examination & Inspection

Has the lifting equipment been thoroughly examined before first use?	**Yes**
Is it inspected, where appropriate, at suitable intervals?	**Yes**

Result & Actions

Overall Result	**Pass - Fit for Continued Use**

Details of any defects found / actions required

Slates slipped near the valley; battens sound. Lead flashing to the chimney needs re-dressing.

Photo of defect (if applicable)



Photo 1

Signature

Inspector Signature

Andy Admin
04/11/2026 10:00

Date

04 Nov 2026

Media summary

Photo 1