

Inspection Analysis Report

Powered by Real Estate Copilot

11409 107th place NE, Kirkland, WA 98033 • April 05, 2026

Prepared by Peipei Guo

Purchase Recommendation

BUY

Confidence: 90%

This property is in good overall condition with no critical or major issues identified. The inspection revealed only minor maintenance items totaling an estimated \$850–\$3,200 in repairs, primarily related to roof upkeep and grading adjustments around the foundation. This is a solid home that requires only routine maintenance and a few low-cost improvements.

Cost & Issue Summary

Estimated Repair Cost	\$850 – \$3,200
Critical Issues	0
Major Issues	0
Minor Issues	4
Informational	6

Key Concerns

- Grading around the foundation may not slope adequately away, risking potential water intrusion over time
- Heat exchanger could not be fully inspected and warrants a dedicated HVAC evaluation

- Roof vents and penetrations show signs of rust/corrosion requiring ongoing maintenance

Full Findings

The inspection identified 10 items. Review each item below and consult with your agent and contractor before making a purchase decision.

1	Minor	Electrical panel lacks full and proper labeling of circuits	\$100–\$300	Have an electrician label all circuits clearly for easier id
2	Minor	Debris accumulation on roof surface can clog gutters, downspouts, and drains, an	\$150–\$400	Clean debris off the roof surface on an annual basis as part
3	Minor	Rust and corrosion may be present on roof vents and penetrations requiring maint	\$100–\$500	Inspect and treat any rust and corrosion on roof vents and p
4	Informational	Water heater TPR valve and discharge pipe present and functional	N/A	No action required. TPR valve and discharge pipe are properl
5	Informational	Water heater has a typical life expectancy of 8-12 years; age and condition shou	N/A	Monitor the water heater's age and condition; plan for repla
6	Informational	Heat exchanger condition could not be fully inspected; general function check on	N/A	Contact an HVAC company for a comprehensive inspection of th
7	Informational	Thermostats and controls found generally serviceable and functional	N/A	No action required. Thermostats and controls are functional.
8	Minor	Grading around the structure may not adequately slope away from the foundation,	\$500–\$2,000	Ensure the grade slopes away from the structure at least 6 i
9	Informational	Foundation should be regularly monitored for cracks, shifting, or water intrusio	N/A	Regularly monitor the foundation for any signs of cracks, sh
10	Informational	Natural gas service present; visible gas lines should be checked for corrosion	N/A	If corrosion is observed on visible gas lines, have the util

Disclaimer: This report is generated by AI and is intended for informational purposes only. All cost estimates are approximate ranges and may vary. This report does not replace a professional home inspection or legal advice. Always consult qualified professionals before making real estate decisions.