TrustMark Retrofit Inspection Report

Job Reference: TM-77812

Property: 5 Oak Avenue, St Albans, Hertfordshire AL3 5PQ

Number of non-compliances: 2

NC 1 - Loft insulation compressed by stored boxes at eaves.

Remedial action: Remove stored items and re-lay insulation to 270mm depth.



NC 2 - Gas boiler flue terminal too close to opening window.

Remedial action: Gas Safe engineer to reposition flue terminal per manufacturer.

