

SPREADSHEET 1: OPERATIONS								
PART NO	OPER.1	OPER.2	OPER.3	OPER.4	OPER.5	OPER.6	OPER.7	OPER.8
PW-STR-001-M	Measure & mark	Cutting	Deburr	Bending	Inspection	Surface Finishing	Inspection	
PW-STR-002-M	Measure & mark	Cutting	Deburr	Bending	Milling	Surface Finishing	Inspection	
PW-STR-003-M	Measure & mark	Cutting	Milling	Drilling	Welding	Deburr	Inspection	
PW-STR-004-M	Measure & mark	Cutting	Milling	Deburr	Surface Finishing	Inspection		
PW-STR-005-M	Measure & mark	Cutting	Milling	Drilling	Deburr	Surface Finishing	Inspection	
PW-STR-006-M	Measure & mark	Cutting	Milling	Drilling	Deburr	Welding	Surface Finishing	Inspection
PW-STR-007-M	Measure & mark	Cutting	Deburr	Milling	Surface Finishing	Inspection		
PW-STR-008-M	Measure & mark	Cutting	Deburr	Milling	Surface Finishing	Inspection		
PW-STR-009-M	Measure & mark	Turning	Cutting	Milling	Assemble	Testing	Inspection	
PW-STR-010-M	Measure & mark	Turning	Cutting	Milling	Inspection	Deburring	Cleaning	