

DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/075

Issued By: M.R Approved By: HOD Mechanical

SOP FOR THE REPLACEMENT OF DPC PAN WITH ROLLER

Scope: To replace the DPC Pan & Roller

Responsibility: Engineer.

Accountability: Section Head.

PPE:

1. Safety helmet.

- 2. Safety shoe.
- 3. Mask.
- 4. Safety goggles.
- 5. Gloves.
- 6. Ear plugs.

TOOLS:

- 1. spanner set
- 2. Crowbar

Hazard Analysis:

<u>Risks associated:</u> <u>Mitigating Measures</u>

Fall of person

Avoid oil spillage, if spilled clean it immediately.

- > Empty of the material from the pans and stop the DPC
- > Take the LOTO for the DPC and inlet / outlet feeding drives
- > Take the hot work permit.
- > Use PPE's (leather hand gloves, hand gloves, goggles, dust mask, safety shoes)
- > Allow the persons to work, clean the working place and remove safety guards
- Hang the tested chain block above the bucket; tie the tested wire rope sling to the bucket.

1/3 (SOP-75)



DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/075

Issued By: M.R Approved By: HOD Mechanical

SOP FOR THE REPLACEMENT OF DPC PAN WITH ROLLER

- > Remove the pan holding bolts with proper care and attention.
- > Lift the pan with chain block with proper care and attention.
- **Remove the pan with rollers with proper care and attention.**
- Fixed the new pan with rollers with proper care and attention.
- > Tightening the pan holding bolts as per specified torque.
- Release the chain block and cross check the sitting of the roller of the rail.
- **Remove the chain block, scrap material, manpower and fix the safety guards.**
- If want to replace another bucket LOTO to be cleared and after taking the position take LOTO again fallow same steps as above.
- Clear the LOTO and inform to the CCR, operator in local mode and check any abnormality.
- > Give the clearance to CCR operator run DPC auto mode.
- > After 8 hrs of operation check the bolt condition and refight.

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

ISA is enclosed below.

2/3 (SOP-75)



DALMIA CEMENT (B) LIMITED - ARIYALUR

MECHANICAL SOP

Issue No. 02 Rev. No: 00 Effective Date: 01.11.2019 SOP/MEC/075

Issued By: M.R Approved By: HOD Mechanical

SOP FOR THE REPLACEMENT OF DPC PAN WITH ROLLER

JOB SAFETY ANALYSIS: (JSA)

Job Safety Analysis	Job: Replacement DPC Bucket or roller	Date: 01 – 09 - 2013	Analysis by: Section Engineer	Reviewed by: Section Head
Title of employee doing job : Section engineer	Supervisor: Section Engineer	Department: Mech	Section: Raw Mill, Cement Mill Coal mill	Approved by: HOD Mecanical

SI. No	Sequence of Basic Job Steps.	Potential Hazards.	Recommended Safe Job Procedure.	What could go wrong?	Corrective action.
1	Bucket or roller bolts removing.	Fingers may entrap	Hold at the proper place	May fall down	Use lifting tackles
2	Bolts Loosening or tightening	Hand may entrap	Work with more comfort	Dust may fall on eyes.	Clean the spot before start & use Gaggles
3	Rotation in between for positioning	Unexpected run	Do not compromise of LOTO		

3/3 (SOP-75)