

DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR



INSTRUMENTATION MANUAL

Issue No. 01Rev. No: 02Effective Date: 20.09.2017SOP/INST/015Issued By: M.RApproved By: HOD - INSTRUMENTATION

SOP for Checking of Signals

Scope: To check the signals.

Responsibility: Instrumentation technician.

Accountability: Instrumentation - Section Engineer.

PPE:

- Safety helmet
- Safety shoe
- Mask
- Goggles
- Hand gloves
- Safety belt

Tools required:

- Multimeter
- Tester
- Screw Driver

Hazard Analysis:

Risks associated Mitigating Measures

Electrocution Use Insulated hand glove



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR INSTRUMENTATION MANUAL



Issue No. 01Rev. No: 02Effective Date: 20.09.2017SOP/INST/015Issued By: M.RApproved By: HOD - INSTRUMENTATION

SOP for Checking of Signals

Procedure:

- 1 Use PPE's hand gloves, nose mask, and goggles.
- 2 Use Multimeter with insulated probes and insulated line tester.
- 3 Ensure the signal interlocks and block the interlock if necessary.
- 4 Switch off the power supply.
- 5 Ensure the cable connections.
- 6 Ensure the field sensors condition.
- 7 Ensure the fuses for healthy condition.
- 8 After confirming the healthy conditions of Point No 5,6 & 7 Switch on the supply.
- 9 Confirm the signal in CCR.
- 10 Retrieve the blocked condition.
- 11 Give the clearance to operation.

Emergency / Emergency Shut OFF:

1. If any unconsciousness is there, give First aid and inform to the Safety department or Call Emergency number 3108/9865152222/9750963761.

Records/Annexure:

1. JSA as enclosed below.



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR



INSTRUMENTATION MANUAL

Issue No. 01 Rev. No: 02 Effective Date: 20.09.2017 SOP/INST/015
Issued By: M.R Approved By: HOD - INSTRUMENTATION

SOP for Checking of Signals

JOB SAFETY ANALYSIS:(JSA)

Job Safety Analysis	Job: CHECKING OF SIGNALS	Date: 20.09.2017	Analysis by:	Reviewed by:
Title of employee doing job: INST - TECHNICIAN	Supervisor: SECTION ENGINEER	Department: INSTRUMENTATI ON	Section: CRUSHER,RA WMILL,PYRO ,CEMENT MILL &PACKING PLANT	Approved by:

Req'd/recommended PPE: SAFETY HELMET, SAFETY SHOES, GOGGLES, DUST MASK, HAND GLOVES

Sequence of Basic Job Steps	Potential Hazards	Recommended Safe Job Procedure	What Could Go Wrong	Corrective Action
1 OPEN THE JUNCTION BOX & BLOWER THE TERMIANAL BLOCKS	DUST MAY COME OUT OF THE JUNCTION BOX	WEAR GOOGLES,HAND GLOVES & NOSE MASK BEFORE BLOWERING	COUGHING, EYE IRRITATION MAY OCCUR	USE GOOGLES, DUST MASK AND HAND GLOVES
2.CHECK THE SIGNALS BY USING MULTIMETER WITH INSULATED PROBES	LIVE SUPPLY IS EXPOSED AT THE MEASURING POINT NEARTHE PROBE	ENSURE THE PROBE IS PROPERLY INSULATED	RESULT IN ELECTROCUT ED	USE INSULATED HAND GLOVES
3. TIGHTEN THE TERMINAL BLOCKS USING	LIVE SUPPLY IS EXPOSED AT THE	ENSURE THE METALLIC PART	RESULT IN ELECTROCUT ED	USE INSULATED HAND



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR INSTRUMENTATION MANUAL



Issue No. 01	Rev. No: 02	Eff	fective Date: 20.09.2017	SOP/INST/015		
Issued By: M.R			Approved By: HOD - INST	RUMENTATION		
SOP for Checking of Signals						

SCREW	METTALIC	OF THE	GLOVES(OR)
DRIVER/TESTER	PART OF THE	TESTER/SCREW	INSULATE
	SCREW	DRIVER IS	THE SCREW
	DRIVER/	INSULATED	DRIVER/
	TESTER.	PROPERLY.	TESTER USING
			INSULATION
			TAPE