

Issue No. 01

DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR INSTRUMENTATION DEPARTMENT



WI-1(SP-8; AM-7)

INSTRUMENTATION DEPARTMENT

Effective Date: 01.11.2010

Issued By: M.R Approved By: HOD-INSTRUMENTATION

CALIBRATION PROCEDURE FOR BELT WEIGHER

CALIBRATION PROCEDURE FOR BELT WEIGHER:

Rev. No: 00

The Instrument engineer takes action as follows, for calibration:

- 1.1 TARE ADJUSTMENT:
- 1.1.1 Run belt empty for 15 minutes.
- 1.1.2 Go to calibration mode.
- 1.1.3 Press Tare
- 1.1.4 TPH rate indication becomes zero.
- 1.1.5 If not zero, repeat step 1 to 4.
- 1.2 SPAN ADJUSTMENT:
- 1.2.1 Run belt empty.
- 1.2.2 Apply the known test weights on both sides of load cell freely
- 1.2.3 IF TPH indication will appear corresponding to the weights applied, no need to span Adjustment
- 1.2.4 IF TPH indication not match with applied weights
- 1.2.5 If error is less than 5%, enter the KOR value which is shown by Intecont Plus (0.95---1.05) In D02
- 1.2.6 TPH indication will appear corresponding to the weights applied.
- 1.2.7 IF not, repeat from step 1 to 5
- 1.3 Record the observations in the Instrument calibration format F-1/WI-21(SP-8; AM-7)



DALMIA CEMENT (B) LIMITED – CEMENT PLANT ARIYALUR



INSTRUMENTATION DEPARTMENT

Issue No. 01	Rev. No: 00	Effective Date: 01.11.2010	WI-1(SP-8; AM-7)
--------------	-------------	-----------------------------------	------------------

Issued By: M.R Approved By: HOD-INSTRUMENTATION

CALIBRATION PROCEDURE FOR BELT WEIGHER

2.0 CONNECTED DOCUMENT:

F-1/WI-21(SP-8; AM-7) CALIBRATION OF BELT WEIGHER

MINES BELT WEIGHER CAPACITY 1250 TPH

TEST WEIGHTS in Kg 20.0 64.8 30.0 97.2 40.0 129.6