Veikko Vikkelä Field Engineer · 09:14
Changed the SFP on transmission node TRN-042. Link is up and alarms cleared, but traffic is still not coming back.

Erkki Expert Network Expert · 09:22
That's it. Disable the interface, wait a little, then enable it again. Don't reboot the whole unit unless that fails.

Veikko Vikkelä 09:26
Is this documented somewhere?

Erkki Expert 09:27
Not that I know of. We've just learned it over the years.

---

a Teams thread · Elisa's example file, unchanged

The link came up. No traffic.

Erkki knew the fix.

It lives in one chat.

The next person starts from zero. The agent that is meant to help cannot see it at all.

THE ANSWER

Silent context remembers it.



READ AS WRITTEN

The chat and the email, exactly as they are.



PINNED TO THE UNIT

TRN–042, in Erkki's own words, and which units he said it covers.



WHO SAID IT, AND WHEN

Erkki · Teams · 14.10. Dated from the moment the part was changed.



ONE CALL FOR THE AGENT

What to do next, and where that came from. Or: check first. Or: I don't know, ask these people.

Nobody fills in anything for the system, and the system **never starts a conversation** with anyone. An unclear case waits with its reason.

ONE CALL FOR THE AGENT

A week later, the same fault on another unit.

PROPOSE **TRN-051** · same class as where it was seen · bounce the interface

Disable the interface, wait a little, then enable it again

Held back	**No reboot or hardware replacement before a failed bounce is reported.**
Counters	zero, read from the device by the agent itself
Why this unit	Observed on TRN-042. TRN-051 is the same class, but the scope "These old units" is undefined, so reaching this unit is an inference.
What would change this	A report that this failed, which lifts the prohibition.

Erkki's step, with its source.

The counters, read from the device itself.

No reboot before the lighter fix has failed.

Then the record fills itself in. What the technician did, and that it worked, comes from the device's own events. Nobody reported anything.

FROM THE DEVICES **TRN-051** · nobody wrote this down

The agent proposed	Disable the interface, wait a little, then enable it again
A person did	Disabled and enabled ge-0/0/1, seen on the device at 2026-10-21T10:53:00
The outcome	Counters rising afterwards

DOUBT

It knows when not to trust itself.

AFTER A FIRMWARE UPDATE

Check again, on that unit only. Nothing expires by a calendar.


WHERE THE FIX DID NOT HELP

Erkki narrowed the advice to the old units. It is no longer offered on the new one.

WHEN TWO EXPERTS DISAGREE

Both stay visible with their sources. No side is taken; the counters are read first.







It shows where advice came from and what was reported about it, **not whether it is true.** It scores advice, **never people.**

MEASURED, AND THE LIMITS

Runs with no model and no key.

MEASURED, FROM THE RECORDED ANSWERS

154 tests pass

11 / 11 sources found in the truth set; merged 7/7, unit 4/4, time 7/7

1 of 16 wrong on sources the rule author never read; 0, 0, 0, 1, 1 in five repeats

Passed a clean install from the README, no key

No edits the graph export loads into Neo4j 5 as it is

WHAT IT DOES NOT CLAIM

01 It never starts a conversation with an expert.

02 It shows where advice came from, not whether it is true.

03 It scores advice, never people.

04 Everything but Elisa's two example files is simulated. The numbers describe that data only.

`github.com/pkorrrhonen-cmd/silent-context` · MIT · Petri Korhonen