

FactoryIQ Demo Corpus — CNC-01_Maintenance_Report_v1.0.pdf

Document Family: CNC-01_Maintenance_Report | Revision: 1.0

Findings

Maintenance report MR-018 records repeated E42 alarms associated with a loose coolant sensor connection and low coolant circulation.

Corrective action

The sensor connection was corrected and the machine was tested. If E42 returns, inspect the sensor connection and coolant circulation.