

FactoryIQ Demo Corpus — CNC-01_RCA_E42_v1.0.pdf

Document Family: CNC-01_RCA_E42 | Revision: 1.0

Root cause

The RCA identifies an intermittent coolant sensor connection as the root cause associated with E42.

Preventive action

Inspect the coolant sensor connection and coolant circulation during relevant maintenance checks.