to the bath-cabinet, can be regulated with perfect safety, if judgment is exercised in keeping the boiler supplied with sufficient water to generate the vapor as rapidly as exhausted, and in keeping enough water in it to prevent collapse; which only could result from overheating the empty boiler.

The bath should be thoroughly heated before the patient enters, and all qualms as to suffocating will disappear as soon as perspiration ensues. A gentle friction can be effected by rubbing, either with the palm of the hand or with a crash towel, on the chest, legs, arms, neck, and face, and the scurf skin will become detached in an astounding manner. The temperature should range from 90 to 120 degrees. Occasionally a patient may experience excellent results by a higher temperature. The period of vaporizing should not exceed twenty-five minutes,—about ten minutes after perspiration commences. The electricity is administered—the negative with round electrode in the foot-tub, or, as sometimes ordered, in No. 7 electrode on the seat, covered with a wet towel for the patient to sit upon; and the positive in the sponge-cup passed down the spine slowly from the base of brain, diverging ONLY when reaching the lumbar region, when the sponge-cup may be passed obliquely from the median line of the spine to one hip, then to the other. The patient must sit forward on the seat, that the arm of the operator may have free action and admit of lifting the sponge-cup off the patient, when an interrupted return from the coccyx to basilar is made; for again it is urged by the author, that the electrization should always