

CONNECTORS

J1: Power supply

1: +5V 2: GND

J2: TTL serial port

1: TXD 1: RXD 1: GND

J3: RS232C serial port

1: TXD 2: RXD 3: GND **JUMPERS** 

JP1: reset

JP2-3: operation modes

Op. mode JP3 JP2

Mode #0 OFF OFF Mode #1 OFF ON Mode #2 ON OFF

Mode #3 ON ON