

## FIRST INSPECTION REPORT

**INSURED/POLICYHOLDER: LUCAS BENOIT** 

ADDRESS: TORONTO, ON M4P 1Z2

**INSURER: NORTHSHORE INSURANCE** 

**CLAM #: PR3766** 

ADJUSTER/ CLAIM REP: FALCON HANDLER

DATE OF INSPECTION: MARCH 12, 2025

DATE OF LOSS: MARCH 9, 2025

DATE OF REPORT: MARCH 13, 2025

**TYPE OF LOSS: STORM** 

Front Photo:



Image 1

## **CAUSE OF LOSS:**

Heavy rains flooded the basement and damaged electrical outlets.

## **SCOPE OF WORK:**

The following is a brief outline of the work to be completed on the contents portion of this claim.

- 1. Pump out flood water.
- 2. Replace affected wiring.
- 3. Inspect mold presence.
- 4. Install sump pump.
- 5. Replace carpeting.

#### RECOMMENDED RESERVES FOR TRINITY'S INVOLVEMENT:

The estimated cost for Trinity's involvement is as follows:

• Indemnity Work: Should not exceed \$20,425.00 plus HST

Our actual cost will be adjusted once the exact scope of approved work is known. The recommended estimate is only based on visual inspection for reserves setting purposes.

• Trinity Listing & Pricing Expense Reserve: Should not exceed \$4,520.00 plus HST

## RECOMMENDED RESERVES FOR THE TOTAL CONTENTS LOSS:

Based on a visual inspection of the extent of non-salvageable items on the main floor, we believe that the total replacement cost for the non-salvageable items should not exceed \$8,375.00 plus HST.

## **CONCLUSION:**

Once our scope of work is approved, we can attend and begin the pack out process.

Thank You,

#### Mo Waez

Trinity Contents Management mo@trinitycontents.com (647) 613-2246

# **BEDROOM1 AREA**





Image 2 Image 3





# **BEDROOM2 AREA**






Image 2 Image 3





Image 2 Image 3

# **KITCHEN AREA**





Image 2 Image 3





# **LIVING AREA**





Image 2 Image 3





# **STORAGE AREA**







Image 2