

SYNTHETIC SCAN - PAGE 1 - NOT A REAL DOCUMENT

ROUTINE MECHANICAL INSPECTION

REPORT NUMBER:	NG-2026-0417
ASSET:	TRANSFER PUMP P-204
ASSET LOCATION:	PUMP HOUSE B, BAY 3
INSPECTION DATE:	2026-04-17
INSPECTOR:	A. OKONKWO (SYNTHETIC NAME)
INSPECTION STANDARD:	SOP-MECH-014 REV 3

CONDITION SUMMARY

CASING:	SERVICEABLE. LIGHT SURFACE CORROSION, NO THROUGH-WALL LOSS OBSERVED.
COUPLING GUARD:	SERVICEABLE.
BASEPLATE ANCHOR BOLTS:	TWO OF FOUR FOUND LOOSE. TORQUE NOT RECORDED AT THE TIME OF INSPECTION.
SUCTION PRESSURE GAUGE:	ILLEGIBLE. FACE FOGGED READING COULD NOT BE TAKEN.

SYNTHETIC SCAN - PAGE 2 - NOT A REAL DOCUMENT

MEASUREMENTS

VIBRATION, DRIVE END: 7.9 MM/S RMS
VIBRATION, NON-DRIVE END: 4.1 MM/S RMS
BEARING TEMPERATURE, DE: 71 C
BEARING TEMPERATURE, NDE: 58 C
DISCHARGE PRESSURE: 3.4 BAR
SUCTION PRESSURE: NOT RECORDED (GAUGE ILLEGIBLE)
MOTOR CURRENT: 18.2 A

ACCEPTANCE LIMITS APPLIED

VIBRATION ALARM LIMIT: 7.1 MM/S RMS
BEARING TEMPERATURE LIMIT: 80 C

SYNTHETIC SCAN - PAGE 3 - NOT A REAL DOCUMENT

FINDINGS

- F-1 VIBRATION AT THE DRIVE END EXCEEDS THE ALARM LIMIT OF 7.1 MM/S RMS.
RECORDED 7.9 MM/S RMS.
- F-2 TWO BASEPLATE ANCHOR BOLTS ARE LOOSE.
- F-3 SUCTION PRESSURE COULD NOT BE VERIFIED BECAUSE THE GAUGE IS ILLEGIBLE.

DISPOSITION

THE PUMP REMAINS IN SERVICE PENDING CORRECTIVE ACTION. RE-INSPECTION IS
REQUIRED WITHIN 14 DAYS OF THIS REPORT.

SIGNED: A. OKONKWO
COUNTERSIGNED: NOT COUNTERSIGNED AT TIME OF ISSUE