



HINDON GRAPHICS

Manufacturers of: DISPOSAL PLATE, DIE & PAPER PLATE MACHINE

Khasra No. 1032, Saddique Nagar, Meenut Road, Ghaziabad - 201003 (U.P.)
E-mail : hindongraphics123@gmail.com

Ref. No.

INSPECTION AND SERVICE CHARGE REPORT

Company Name: Shri Manjunath Industries

Date of Incident: 23/06/2025

Location: Vijayapura

Inspection Conducted By: Javed (Hindon Graphics)

Purpose: Insurance Claim Submission

Incident Summary

On 23/06/2025, an electrical fire occurred at the Vijayapura unit of Shri Manjunath Industries. The incident resulted in damage to multiple machines and electrical systems. The fire was controlled promptly, but significant losses occurred due to heat, smoke, and short circuits.

Inspection Overview

A detailed inspection was carried out by Javed (Hindon Graphics) to assess the extent of damage and identify the repair or replacement requirements. All observations have been documented below for insurance verification and claim processing.

Observations and Findings


This is the observation regarding Automatic Taper Machine,

Sl. No.	Machine / Equipment	Qty	Observed Damage	Remarks
1	Machine	02	Total M/c Damaged	Needs full replacement

Authorization

Prepared By: Javed (Hindon Graphics)

Designation: Technical Inspector

Signature & Seal: 

Approved By: Authorized Signatory, Shri Manjunath Industries

Date: 16-07-25

For SHRI MANJUNATH INDUSTRIES

Signature & Seal: 
Dr. Javed
Proprietor



AVR PAPER PLATES AND CUPS MACHINES

Manufacturers & Suppliers of

PAPER PLATE MACHINES, PAPER CUP MACHINES & ALL TYPES OF RAW MATERIALS

INSPECTION AND SERVICE CHARGE REPORT

Company Name: SHRI MANJUNATH INDUSTRIES

Date of Incident: 23-06-2025

Location: Vijayapura Inspection

Conducted By: Anish Kumar Reddy

Purpose: Insurance Claim Submission

1. Incident Summary

On June 23, 2025, an electrical fire occurred at the Vijayapura unit of Shri Manjunath Industries. The incident resulted in damage to multiple machines and electrical systems. The fire was controlled promptly, but significant losses occurred due to heat, smoke, and short circuits.

2. Inspection Overview

A detailed inspection was carried out by Anish Kumar Reddy to assess the extent of damage and identify the repair or replacement requirements. All observations have been documented below for insurance verification and claim processing.

3. Observations and Findings

This is the observation regarding the Automatic Buffet Paper Plate Machine

S NO	HSN CODE	PRODUCT DESCRIPTION	MODEL ID	OBSERVED DAMAGE	REMARKS
1	85014010	Motor	C-202	Motor burnt due to short circuit	Needs full replacement
2	85168000	Ceramic heaters	CH-222	Coil damage	Needs full replacement
3	8441	Dies	C-138	De-structured due to Fire	Needs full replacement
4	90318080	Sensors	G-286	Circuit chip failed	Needs full replacement
5	8371000	Panel board	S-348	All components are completely failed	Needs full replacement
6	8531700	Machine wiring	H-284	Wires completely burnt	Wiring needs to be done
7	84818030	Solenoid valve	S-496	Valves completely melted due to fire	Needs full replacement
8	8195099	Oil cooler	C-296	Not in a working state	Needs full replacement
9	84129090	Hydraulic cylinder	H-428	Cylinder rods and seals deformed due to excess heat	Needs full replacement

4. Authorization

prepared By: Anish Kumar Reddy

Designation: Technical Inspector

Approved By: Shri Manjunath Industries

Date: 21-06-25

For AVR PAPERPLATES AND CUPS MACHINES
Proprietor


Signature & Seal: _____

Signature & Seal: _____
C6 PART, BESIDE AJANTHA FOOD COURT, IDA UPPAL, HYDERABAD, TELANGANA-500039

AVR PAPER PLATES AND CUPS MACHINES

Manufacturers & Suppliers of
PAPER PLATE MACHINES, PAPER CUP MACHINES & ALL TYPES OF RAW MATERIALS

INSPECTION AND SERVICE CHARGE REPORT

Company Name: SHRI MANJUNATH INDUSTRIES

Date of Incident: 23-06-2025

Location: Vijayapura Inspection

Conducted By: Anish Kumar Reddy

Purpose: Insurance Claim Submission

1. Incident Summary

On June 23, 2025, an electrical fire occurred at the Vijayapura unit of Shri Manjunath Industries. The incident resulted in damage to multiple machines and electrical systems. The fire was controlled promptly, but significant losses occurred due to heat, smoke, and short circuits.

2. Inspection Overview

A detailed inspection was carried out by Anish Kumar Reddy to assess the extent of damage and identify the repair or replacement requirements. All observations have been documented below for insurance verification and claim processing.

3. Observations and Findings

This is the observation regarding Packing Machine

S NO	PRODUCT DESCRIPTION	MODEL ID	OBSERVED DAMAGE	REMARKS
1	Chamber	C-164	Completely burnt	Needs full replacement
2	Heater	CH-223	Coil cut off	Needs full replacement
3	Blower	C-195	Armature and winding burnt	Needs full replacement
4	Sealer	F-276	Not in	Needs full replacement
5	Machine wiring	H-284	Wires completely burnt	Wiring needs to be done

4. Authorization

Prepared By: Anish Kumar Reddy

Designation: Technical Inspector

Approved By: Shri Manjunath Industries


Date: 24-06-25

For AVR PAPER PLATES AND CUPS MACHINES

 Proprietor

Signature & Seal: _____

For SHRI MANJUNATH INDUSTRIES


 Proprietor

Signature & Seal: _____

C6 PART, BESIDE AJANTHA FOOD COURT, IDA UPPAL, HYDERABAD, TELANGANA-500039