
Trellises Apartments, Florence Ohio



Water issues as further described by Nate:

- 1. Water is getting into the corner unit on the left building
- 2. Water is sitting for a period of time at the base of the hill on the left
- 3. Water pools for a longer time behind building on right, but does not enter the building
- 4. Entire area remains wet for days after a major rain

Objectives

- 1. No water entering structure
- 2. Remove standing water standing water in reasonable amount of time
- 3. Remove sogginess in area in reasonable amount of time