



Brandon Phillips Field Solution


PARJANA®
& PARJANA Distribution



PARJANA®

& PARJANA Distribution

1274 Library Street, Suite 600 | Detroit MI 48226
Phone: 855-PARJANA | www.parjana.com



Brandon Phillips Field Statement of problem

Brandon Phillips ball field is managed by the Cincinnati Reds organization. It is experiencing chronic wet areas, puddles, and flooding. Runoff from the surrounding hillside and the contiguous P & G field exacerbate the problem.

French drains have been installed through parts of the field, and have succeeded in making The infield and left field dry very well. These areas are even playable in the late afternoon after a heavy morning rain. Right center field can take one and maybe two days to dry after a heavy rain.

The Reds will often allow play on the field and have to rope off a section of right field, The Reds would like to have this portion of the field playable when the other part of the field is playable.

Additionally, they would like to stop the erosion that is degrading the field from the hillside runoff. There is also concern that installation of any system in early spring will cause deep rutting in the field, further damaging the surface.

BRANDON PHILLIPS FIELD-CINCINNATI OH
PROPOSAL ESTINAMATED RANGE

March 6, 2014

Customer:	Cincinnati Reds
Job Address:	5425 Winton Ridge Lane
City, State ZIP:	Cincinnati OH 45232
Phone:	513-765-7231
E-mail:	cfrank@reds.com

TERMS OF PROPOSAL

1. Furnish labor and materials for the total installation of PARJANA® EGRP®- as shown in the attached drawing.
 2. All labor and materials for the installation of PARJANA® EGRP® are included.
 3. Warranty of the complete system for 25 years.
 4. System to be install using mats to prevent field damages
-

OPTION 1 – Approx. 327' linear feet of EGRP

Home Plate & surrounding area and fall off from Hill behind home play

Price Range: \$22,000 to \$28,000

OPTION 2 – Approx. 400' linear feet of EGRP

Right center field; eliminate all water coming onto the field, stop run off from hill side

Price Range: \$23,000 to \$28,000

OPTION 3 – Approx. 813' linear feet of EGRP

Install in the right center field to instantly dry area. We would only do this if the water is not eliminated by option 2

**ALL INSTALLATIONS INCLUDE 25 YEARS OF WARRANTY AND MONEY BACK
GUARANTEE (PER PROJECT SPECIFIC DEFINITION)**



PARJANA®

& PARJANA Distribution

1274 Library Street, Suite 600 | Detroit MI 48226
Phone: 855-PARJANA | www.parjana.com

OPTION 1 – Approx. 327' linear feet of EGRP





PARJANA®

& PARJANA Distribution

1274 Library Street, Suite 600 | Detroit MI 48226
Phone: 855-PARJANA | www.parjana.com

OPTION 2 – Approx. 400' linear feet of EGRP





PARJANA®
& PARJANA Distribution

1274 Library Street, Suite 600 | Detroit MI 48226
Phone: 855-PARJANA | www.parjana.com

OPTION 3– Approx. 813' linear feet of EGRP



THIS WARRANTY GIVES YOU SPECIAL LEGAL RIGHTS, & YOU MAY ALSO HAVE OTHER RIGHTS, WHICH VARY FROM STATE TO STATE.



Parjana Distribution, LLC
1274 Library Street, Suite
600
Detroit MI 48226

It is agreed and understood that the PARJANA System takes a minimum of 12 weeks to become fully activated depending on rainfall and soil type. Upon activation, PARJANA Distribution, LLC, warrants the system will meet the determined performance requirements.

This warranty will continue for a period of 25 years to perform as described. The foregoing is our sole warranty. All others warranties, expressed or implied, including any warranty of merchantability or warranty of fitness for a specific purpose, are excluded. The owner's exclusive remedy shall be for correction of defects in workmanship and materials, as set forth above. In no event shall Parjana Distribution LLC be liable for consequential damages, regardless of whether the claim is based on warranty, contract, tort, or otherwise. Should service be required, immediately notify Parjana Distribution LLC. This warranty does not cover leakage from: backing up or plugging of sewers or floor drains; flooding conditions (i.e., surface water through doors, or roof leaks); or condensation caused by high humidity, any negative grade or lack of downspouts.

Job Address: XXXX

Authorized Signature_____

