



TWO-FRAME SURVEY TELEMETRY

Defect ID: 1ee43161-c0ce-4269-89fc-dac5c8627e5c Current Scan: 2026-09-08 10:00:00 UTC
Coordinates: 12.840700, 80.153500 Time Delta: Initial Scan (Base Frame)

Two-Frame Spatial-Temporal Comparative Metrics

CURRENT DEFECT AREA

0.6500 m²
Prev: None (Base Frame)

AREA DELTA %

+0.0%
State: New

MUNICIPAL PRIORITY

Rank 8 / 10
Severity: High

Civil Engineering Advisory (Gemini 1.5 Flash)

Root Cause Analysis

Asphalt fatigue cracking aggravated by subsurface water seepage.

Recommended Remediation

Full-depth asphalt patching and edge drainage installation.