



TWO-FRAME SURVEY TELEMETRY

Defect ID: 2faf0114-ed58-4c2a-9dd3-c4d3da3e5751

Current Scan: 2026-09-15 10:00:00 UTC

Coordinates: 12.840610, 80.153408

Time Delta: 7d 0h ago

Two-Frame Spatial-Temporal Comparative Metrics

CURRENT DEFECT AREA

0.3500 m²

Prev: 0.6500 m²

AREA DELTA %

-46.2%

State: Improving

MUNICIPAL PRIORITY

Rank 8 / 10

Severity: High

Civil Engineering Advisory (Gemini 1.5 Flash)

Root Cause Analysis

Asphalt fatigue cracking aggravated by subsurface water seepage.

Recommended Remediation

Full-depth asphalt patching and edge drainage installation.