



TWO-FRAME SURVEY TELEMETRY

Defect ID: 7c0ad89d-defa-4674-900a-7fce95047746 Current Scan: 2026-09-08 10:00:00 UTC
Coordinates: 12.840610, 80.153408 Time Delta: 7d 0h ago

Two-Frame Spatial-Temporal Comparative Metrics

CURRENT DEFECT AREA

0.6500 m²

Prev: 0.5000 m²

AREA DELTA %

+30.0%

State: Worsening

MUNICIPAL PRIORITY

Rank 8 / 10

Severity: High

Civil Engineering Advisory (Gemini 1.5 Flash)

Root Cause Analysis

Asphalt fatigue cracking aggravated by subsurface water seepage.

Recommended Remediation

Full-depth asphalt patching and edge drainage installation.