



TWO-FRAME SURVEY TELEMETRY

Defect ID: eecdb757-46bc-425d-b760-ba08f7ded2c1 Current Scan: 2026-09-01 10:00:00 UTC
Coordinates: 12.840600, 80.153400 Time Delta: Initial Scan (Base Frame)

Two-Frame Spatial-Temporal Comparative Metrics

CURRENT DEFECT AREA

0.5000 m²

Prev: None (Base Frame)

AREA DELTA %

+0.0%

State: New

MUNICIPAL PRIORITY

Rank 8 / 10

Severity: High

Civil Engineering Advisory (Gemini 1.5 Flash)

Root Cause Analysis

Asphalt fatigue cracking aggravated by subsurface water seepage.

Recommended Remediation

Full-depth asphalt patching and edge drainage installation.