

**Unit Information**  
**Unit #:** 16643K  
**Unit Description:** 2016 WABASH  
**Year:** 2016  
**Make:** WABASH NATIONAL CORP.  
**Model:** TRAILER  
**License:**  
**Serial #:** 1JJV532D1GL891828

**Repair Shop**  
**Facility:** 511  
**Shop:** MAIN  
**Priority:**  
**Created By:** ARBS511  
**Open Date:** Nov 15, 2025  
**Close Date:**  
**Scheduled Start Date:** Nov 15, 2025  
**Requested Completion Date:**  
**Status:** Open  
**Approval Date:**

**Work Order 2761084**

**Comments:**

DUE:11/02/25 PRV: 8/04/25

| Line                                                                                                                                      | Billable | Reason                      | Activity      | Repair Description                           | Qty / Hours | Rate  | UOM |
|-------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------------------|---------------|----------------------------------------------|-------------|-------|-----|
|                                                          |          |                             |               |                                              |             |       |     |
| 1                                                                                                                                         | B        | (08) PREVENTIVE MAINTENANCE |               | (PM 005-50) PERFORM PM TRAILER SERVICE       |             |       |     |
|                                                                                                                                           |          |                             | Labor         | (1162) CLAYTON HATHAWAY                      | 1.43        | _____ |     |
|                                                                                                                                           |          |                             | Labor         | (1091) SHAWN BOERSEMA                        | 1.08        | _____ |     |
|                                                                                                                                           |          |                             | Supplies      |                                              | 1.00        | _____ |     |
|                                                                                                                                           |          |                             | Environmental |                                              | 1.00        | _____ |     |
| <b>Complaint:</b><br>Trailer PM Service                                                                                                   |          |                             |               |                                              |             |       |     |
| <b>Cause:</b><br>due for PM                                                                                                               |          |                             |               |                                              |             |       |     |
| <b>Correction:</b><br>finish later, 1162. Trailer PM Service completed. 1091<br>Additional time on this task freeing up clevis pins. 1162 |          |                             |               |                                              |             |       |     |
| <b>Line Subtotal</b>                                                                                                                      |          |                             |               |                                              |             |       |     |
|                                                        |          |                             |               |                                              |             |       |     |
| 2                                                                                                                                         | B        | (08) PREVENTIVE MAINTENANCE |               | (13 010-01) ADJUST AIR TYPE POWER BRAKES (SE |             |       |     |
|                                                                                                                                           |          |                             | Supplies      |                                              | 1.00        | _____ |     |

| Line | Billable | Reason                                                                                                                                                                                          | Activity      | Repair Description                           | Qty / Hours | Rate | UOM |
|------|----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|----------------------------------------------|-------------|------|-----|
|      |          |                                                                                                                                                                                                 | Environmental |                                              | 1.00        |      |     |
|      |          | <b>Complaint:</b><br>Slack adjuster clevis pins seized up                                                                                                                                       |               |                                              |             |      |     |
|      |          | <b>Cause:</b><br>age, rust                                                                                                                                                                      |               |                                              |             |      |     |
|      |          | <b>Correction:</b><br>Pressed out rusted clevis pins.1162                                                                                                                                       |               |                                              |             |      |     |
|      |          |                                                                                                                                                                                                 | Line Subtotal |                                              |             |      |     |
|      |          |                                                                                                                |               |                                              |             |      |     |
| 3    | B        | (08) PREVENTIVE<br>MAINTENANCE                                                                                                                                                                  |               | (18 004-01) ADJUST TRAILER, CONVERTER, TAG & |             |      |     |
|      |          |                                                                                                                                                                                                 | Labor         | (1091) SHAWN BOERSEMA                        | 0.39        |      |     |
|      |          |                                                                                                                                                                                                 | Supplies      |                                              | 1.00        |      |     |
|      |          |                                                                                                                                                                                                 | Environmental |                                              | 1.00        |      |     |
|      |          | <b>Complaint:</b><br>Right side hub caps leaking, oil levels full                                                                                                                               |               |                                              |             |      |     |
|      |          | <b>Cause:</b><br>center caps loose                                                                                                                                                              |               |                                              |             |      |     |
|      |          | <b>Correction:</b><br>Found flow-through center caps were loose. Tightened caps,<br>will need wheels reclocked to line up valve stem hoses when<br>wheels are reinstalled after brake job. 1091 |               |                                              |             |      |     |
|      |          |                                                                                                                                                                                                 | Line Subtotal |                                              |             |      |     |
|      |          |                                                                                                              |               |                                              |             |      |     |
| 4    | B        | (08) PREVENTIVE<br>MAINTENANCE                                                                                                                                                                  |               | (16 008-01) ADJUST AIR RIDE SUSPENSION       |             |      |     |
|      |          |                                                                                                                                                                                                 | Labor         | (1091) SHAWN BOERSEMA                        | 0.65        |      |     |
|      |          |                                                                                                                                                                                                 | Supplies      |                                              | 1.00        |      |     |
|      |          |                                                                                                                                                                                                 | Environmental |                                              | 1.00        |      |     |

| Line                                                                                                                                                                                 | Billable | Reason                      | Activity      | Repair Description                           | Qty / Hours | Rate | UOM |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------------------|---------------|----------------------------------------------|-------------|------|-----|
| <b>Complaint:</b><br>Tandem slide lock pins not extending all the way, clip coming off rear slide actuator cylinder.                                                                 |          |                             |               |                                              |             |      |     |
| <b>Cause:</b><br>age, rust                                                                                                                                                           |          |                             |               |                                              |             |      |     |
| <b>Correction:</b><br>Replaced clip style clevis pins with bolts and lock nuts. Found slider box was slightly off-center. Moved slider with pry bar and all lock pins extended. 1091 |          |                             |               |                                              |             |      |     |
| <b>Line Subtotal</b>                                                                                                                                                                 |          |                             |               |                                              |             |      |     |
|                                                                                                     |          |                             |               |                                              |             |      |     |
| 5                                                                                                                                                                                    | B        | (08) PREVENTIVE MAINTENANCE |               | (13 007-01) ADJUST BRAKE LINES AND FITTINGS  |             |      |     |
|                                                                                                                                                                                      |          |                             | Labor         | (1091) SHAWN BOERSEMA                        | 1.22        |      |     |
|                                                                                                                                                                                      |          |                             | Supplies      |                                              | 1.00        |      |     |
|                                                                                                                                                                                      |          |                             | Environmental |                                              | 1.00        |      |     |
| <b>Complaint:</b><br>Brake fitting leaking at right rear brake chamber                                                                                                               |          |                             |               |                                              |             |      |     |
| <b>Cause:</b><br>Fitting leaking                                                                                                                                                     |          |                             |               |                                              |             |      |     |
| <b>Correction:</b><br>Removed hose end and installed new 3/8" Swivel field end. 1091                                                                                                 |          |                             |               |                                              |             |      |     |
| <b>Line Subtotal</b>                                                                                                                                                                 |          |                             |               |                                              |             |      |     |
|                                                                                                   |          |                             |               |                                              |             |      |     |
| 6                                                                                                                                                                                    | B        | (08) PREVENTIVE MAINTENANCE |               | (14 002-01) ADJUST BUMPERS & ATTACHING PARTS |             |      |     |
|                                                                                                                                                                                      |          |                             | Labor         | (1091) SHAWN BOERSEMA                        | 0.40        |      |     |
|                                                                                                                                                                                      |          |                             | Supplies      |                                              | 1.00        |      |     |
|                                                                                                                                                                                      |          |                             | Environmental |                                              | 1.00        |      |     |

| Line                                                                                                                    | Billable | Reason                         | Activity      | Repair Description                                  | Qty / Hours | Rate  | UOM |
|-------------------------------------------------------------------------------------------------------------------------|----------|--------------------------------|---------------|-----------------------------------------------------|-------------|-------|-----|
| <b>Complaint:</b><br>Rear ICC bumper mounting bolts loose                                                               |          |                                |               |                                                     |             |       |     |
| <b>Cause:</b><br>Age, vibration                                                                                         |          |                                |               |                                                     |             |       |     |
| <b>Correction:</b><br>Tightened loose ICC bumper mounting bolts. 1091                                                   |          |                                |               |                                                     |             |       |     |
| Line Subtotal                                                                                                           |          |                                |               |                                                     |             |       |     |
|                                        |          |                                |               |                                                     |             |       |     |
| 7                                                                                                                       | B        | (08) PREVENTIVE<br>MAINTENANCE |               | (04 005-03) EXCHANGE, NEW FAIRING - CHASSIS         |             |       |     |
|                                                                                                                         |          |                                | Labor         | (1091) SHAWN BOERSEMA                               | 1.68        | _____ |     |
|                                                                                                                         |          |                                | Supplies      |                                                     | 1.00        | _____ |     |
|                                                                                                                         |          |                                | Environmental |                                                     | 1.00        | _____ |     |
| <b>Complaint:</b><br>Trailer fairing side rods broken                                                                   |          |                                |               |                                                     |             |       |     |
| <b>Cause:</b><br>most likely impact, vibration                                                                          |          |                                |               |                                                     |             |       |     |
| <b>Correction:</b><br>Modified good used side support rod to fit brackets.<br>Replaced missing side fairing bolts. 1091 |          |                                |               |                                                     |             |       |     |
| Line Subtotal                                                                                                           |          |                                |               |                                                     |             |       |     |
|                                      |          |                                |               |                                                     |             |       |     |
| 8                                                                                                                       | B        | (08) PREVENTIVE<br>MAINTENANCE |               | (13 010-03) EXCHANGE, NEW AIR TYPE POWER BRAKES (SE |             |       |     |
|                                                                                                                         |          |                                | Supplies      |                                                     | 1.00        | _____ |     |
|                                                                                                                         |          |                                | Environmental |                                                     | 1.00        | _____ |     |
| <b>Complaint:</b><br>Brake shoes at 5/16"                                                                               |          |                                |               |                                                     |             |       |     |
| Line Subtotal                                                                                                           |          |                                |               |                                                     |             |       |     |

| Line                                                                                                                                                           | Billable | Reason                         | Activity      | Repair Description                       | Qty / Hours | Rate  | UOM |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|--------------------------------|---------------|------------------------------------------|-------------|-------|-----|
|                                                                               |          |                                |               |                                          |             |       |     |
| 9                                                                                                                                                              | B        | (08) PREVENTIVE<br>MAINTENANCE |               | (17 002-06) INSPECT TIRE REAR            |             |       |     |
|                                                                                                                                                                |          |                                | Labor         | (1162) CLAYTON HATHAWAY                  | 1.00        | _____ |     |
|                                                                                                                                                                |          |                                | Supplies      |                                          | 1.00        | _____ |     |
|                                                                                                                                                                |          |                                | Environmental |                                          | 1.00        | _____ |     |
| <b>Complaint:</b><br>Nail in right front tire                                                                                                                  |          |                                |               |                                          |             |       |     |
| <b>Correction:</b><br>replace tire dismount, clean rim, remount, air up and<br>install torque rim                                                              |          |                                |               |                                          |             |       |     |
| <b>Line Subtotal</b>                                                                                                                                           |          |                                |               |                                          |             |       |     |
|                                                                               |          |                                |               |                                          |             |       |     |
| 10                                                                                                                                                             | B        | (08) PREVENTIVE<br>MAINTENANCE |               | (13 002-08) OVERHAUL REAR BRAKES & DRUMS |             |       |     |
|                                                                                                                                                                |          |                                | Labor         | (1162) CLAYTON HATHAWAY                  | 5.99        | _____ |     |
|                                                                                                                                                                |          |                                | Supplies      |                                          | 1.00        | _____ |     |
|                                                                                                                                                                |          |                                | Environmental |                                          | 1.00        | _____ |     |
| <b>Correction:</b><br>replace both axle brakes and drums, everyone of anchor<br>pins<br>gave me a hard time getting them out, torque rims and<br>adjust brakes |          |                                |               |                                          |             |       |     |
| <b>Line Subtotal</b>                                                                                                                                           |          |                                |               |                                          |             |       |     |
|                                                                             |          |                                |               |                                          |             |       |     |
| 11                                                                                                                                                             | B        | (08) PREVENTIVE<br>MAINTENANCE |               | (71 001-03) EXCHANGE, NEW FLOOR ASSEMBLY |             |       |     |
|                                                                                                                                                                |          |                                | Labor         | (1162) CLAYTON HATHAWAY                  | 1.06        | _____ |     |
|                                                                                                                                                                |          |                                | Labor         | (1162) CLAYTON HATHAWAY                  | 5.40        | _____ |     |

| Line | Billable | Reason | Activity      | Repair Description               | Qty / Hours | Rate  | UOM |
|------|----------|--------|---------------|----------------------------------|-------------|-------|-----|
|      |          |        | Part          | (WAB08S0121501) PLATE, THRESHOLD | 1.00        | _____ | EA  |
|      |          |        | Supplies      |                                  | 1.00        | _____ |     |
|      |          |        | Environmental |                                  | 1.00        | _____ |     |

**Complaint:**

DMG diamond plate

**Correction:**

remove diamond plate had to drill out bolts and most of them broke, reinstall new plate had to drill holes in plate and bolt down, had to to Trudell for caulk .caulk around it and clean up mess

**Line Subtotal**