

Package #173

Integrate a pre-engineered microfracture lattice into the drainage floor surface, creating a passive network of channels that open under hydraulic pressure to compensate for viscosity-induced resistance.

Technology Maturity: ENGINEERING_DEFINITION

Transfer Posture: Sponsored Validation

Problem: Documented problem 'hydraulic performance deviation' concerning drainage floor. User-submitted engineering problem (session input): "Why does P-07's drainage floor deviate from the measured water viscosity basis? (reality discrepancy semantics)". [fra_rail_accidents] retrieval status GRAMMAR_MISMATCH (query does not match source grammar: YYYY-MM-DD date floor (\$where date >= X) — engine routing error, not a provider failure (not absence, Art. XXV)) — provider outcome recorded, not treated as absence (Art. XXI.3). [doe_osti] 10 records retrieved live (2026-2026). Illustrative records: 'Evaluating the Analytical Capabilities of RAM In-situ Diagnostics'; 'Resonant Acoustic Mixing of Dense Pastes: Role of Adhesion and Viscosity'. LIMITS STAMPED INLINE: literature context establishes the problem class, not event rates. Problem-existence basis: live records retrieved.

Mechanism: Porefracture structure provides passive hydraulic pathways that modulate flow resistance.

Contents:

- 01 - Executive Technology Brief
- 02 - Engineering Technology-Transfer Dossier
- 03 - Buyer Decision Card
- 04 - Evidence Summary
- 05 - Transfer Manifest

Status: ENGINEERING_DEFINITION. Not physically validated.