

Package #123

Incorporate micro-vibration dampening materials and structures within pacemaker lead insulation to protect internal components from mechanical stress during patient movement

Technology Maturity: ENGINEERING_DEFINITION

Transfer Posture: Sponsored Validation

Problem: Documented recurring problem 'therapeutic_or_diagnostic_output_failure' for pacemaker lead: 10 MAUDE reports across 3 distinct devices (20230811 to 20230812); root-cause evidence from 1 recall records and 10 event narratives (custody attached in the campaign report). MAUDE limitations: incidence UNKNOWN, causation UNVERIFIED (Art. XXI.5). Existing solutions fail because: Why existing solutions fail, per retrieved evidence: 1 recall root-cause descriptions (FDA enforcement records, custody attached); 10 MAUDE event narratives from this mechanism cluster (mdr_text, custody attached). Statements are the providers' own words, cust Unresolved gap: Across the 7 relevant retrieved attempts (a bounded, non-exhaustive set), none measurably addresses: conditions, devices, events, function, intervention, introducing, maintain, malfunction, matching, modes, must, problem, producing, recurring, reported, under,

Mechanism: Vibration-damping systems in automotive suspensions that isolate components from external stressors while maintaining functionality

Contents:

- 01 - Executive Technology Brief
- 02 - Engineering Technology-Transfer Dossier
- 03 - Buyer Decision Card
- 04 - Evidence Summary
- 05 - Transfer Manifest

Status: ENGINEERING_DEFINITION. Not physically validated.