INDUSTRIAL EQUIPMENT INSPECTION REPORT

Report ID: IR-2026-001
Equipment: Cooling Water Pump P-101
Inspection Date: 28-Aug-2026
Department: Maintenance

INSPECTION FINDINGS

---

1. Minor leakage was observed near the mechanical seal.

2. Abnormal vibration of approximately 4.8 mm/s
was recorded during operation.

3. Coupling alignment was found to require correction.

4. No visible cracks were observed on the pump casing.

RECOMMENDATION

The maintenance team recommends:

1. Replacement of the mechanical seal.
2. Correction of coupling alignment.
3. Follow-up vibration measurement after maintenance.

The equipment should be monitored until corrective
maintenance is completed.

INSPECTOR

Maintenance Department
Industrial Operations Division