# Laboratory Safety Checklist

## Before the first run

1. Wear the lab coat and closed shoes.

2. Tie back long hair.

3. Locate the mains switch.

4. Check the earthing.

5. Report a damaged cable.

## Definitions

Earthing: connecting the chassis of the equipment to the ground so that a fault current has a low resistance path.

Mercury thermometer: prohibited in the lab since 2019.

Static charge: discharge by touching a grounded metal plate before handling a module.

## Rules

No food inside the lab.

No mobile at the bench.

Sign the register.

Two students per machine.

Report a burn at once.

## Sign-off

All practicals must be signed by the lab instructor before submission.

The record is verified in the last week of the semester.

A student who has not completed eight practicals is not admitted to the internal assessment.

Contact: lab instructor, room 214, extension 305.