Laboratory Safety Checklist

Before the first run

1. Wear the lab coat and closed shoes.

2. Tie back long hair.

3. Locate the mains switch.

4. Check the earthing.

5. Report a damaged cable.

Definitions

Earthing: connecting the chassis of the equipment to the ground so that a fault current has a low resistance path.

Mercury thermometer: prohibited in the lab since 2019.

Static charge: discharge by touching a grounded metal plate before handling a module.

Rules

No food inside the lab.

No mobile at the bench.

Sign the register.

Two students per machine.

Report a burn at once.

Sign-off

All practicals must be signed by the lab instructor before submission.

The record is verified in the last week of the semester.

A student who has not completed eight practicals is not admitted to the internal assessment.

Contact: lab instructor, room 214, extension 305.