1609.037

NISSEI PLASTIC PHILIPPINES, INC.
Unit 11 Bldg. B Laguna Technopark Standard Factory Bldg. 2 Phase 7
Laguna Technopark-Sez Binan Laguna 4024 Philippines
Tel No 049-544-5670 Fax No 049-544-5647

SERVICE QUOTATION

ATTN: PRICON MICROELECTRONICS INC.,
Sir KOBAYASHI

Q/S NO: QS 160914005
DATE: September 14, 2016
SERVICE REPORT NO: A0212

We thank you for your recent enquiry.
As requested, we are delighted to submit herewith our official quotation for your kind consideration and approval.

Terms of Payment : T/T Remittance 30days After INVOICE date
Validity : October 14, 2016
Machine Model : PN60-5AN MC#:
Serial Number : E00610001K1

DESCRIPTION	Q'TY	U/PRICE	TOTAL
No reading of screw position on the monitor.	1	₱7,000	₱7,000 -
Action taken			
1) Adjustment on the LS27 vertical clearance.			
Checking LS27 sensor no problem.			
Rail encoder have scrached.			
Recommended			
Change SCALE SL33120			
PARTS QUOTATION No QP160913006			
Recommendation			
Change Cylinder and Rod of ejector			

TOTAL	₱7,000 -

This Quotation is exclusive of PARTS fee and TRAVEL expenses
For details of the contents please refer to attached sheet
*** E.. & O.E.***

NISSEI PLASTIC PHILIPPINES INC.

NPPIS007