SERVICE REPORT

JOB NO : 2727 01-00150

Customer PRICON MICROELECTRONICS INC.	Date 06-AUGUST-2016
Person-In Charge MR. GAMBOA Dept ENGG.	P.O. No
Tel Fax	Remark SV-1608004

Job Title MACHINE CHECKING

Model NCI-4(2)-B S/No 00204-6220 Instal/Date 1989 (MFD)

Problem 1. SAFETY INTERLOCK NUMBER 4 (OKAY LAMP) CAN'T SYNCHRONIZE ENERGIZE TOGETHER WITH SAFETY INTERLOCK NUMBER 1, 2 AND 3.

Measures
1. AS PER CHECKING THE NON-REPEAT AUXILIARY RELAY (CRK) IS MAL-FUNCTIONING DUE TO HAMMING AND NOISY OF HIS MAGNETIC COIL.
2. REPLACEMENT OF THIS RELAY (AIDA SPARED PART).
3. TEST RUNNING THE MACHINE AND CHECKING THE SYNCHRONIZE ENERGIZE OF THE FOUR SAFETY INTERLOCK ALL FUNCTIONING AT SAME TIME.
4. AS PER TEST RUNNING NO PROBLEM ENCOUNTERED RELATED TO THE SAID PROBLEM.

Date	Man	Dep	AIDA	Arv	Cus	Dep	Cus	Arv	AIDA	Normal	1½	2	Job Done by
06 AUG.		7	00	8	00	12	00	13	00		4		GEORGE

SPARE PART	Qty	U/Price	Amount
LABOUR CHARGES [NORMAL]	4	US$ 37.5	US$ 150
[1½]			
[2]			
TRANSPORT			
PACKING & DELIVERY CHARGE			
VAT			
TOTAL			US$ 150

Remark
1. AS PER AGREEMENT TO MR. GAMBOA USING FIRST THE AIDA SPARED PART BUT CUSTOMER NEED TO REPLACE THE SAID PART.

Authorised	Confirm	Incharge
		G. CAPE, JR. M.

Work carried out to our complete satisfaction

CHARGEABLE

Checked & confirmed by
Name Roderick T. Gomez
Post Sr. Engineer
Sign
Date 08/06/16

Company Name/Stamp

AIDA GREATER ASIA PHILIPPINES, INC.

CUSTOMER COPY