SERVICE REPORT

JOB NO : 2727 [0][3]–[0][0][1][3][8]

Customer PRICON MICRO-ELECTRONICS. PHILS. INC.	Date JULY 4, 2016
Person-In Charge MR. E. GAMBOA Dept ENG'G.	P.O. No
Tel Fax	Remark SV-1607001

Job Title MACHINE INSPECTION

Model NC1-80(2) S/No 00208-7119, 8797 Instal/Date
NC1-45(2) 00204-6220

Problem

1) MACH. No. 1 NC1-45(2) S/N 00204-6220 – TUC OIL LEAKS AT ROTARY JOINT INCLUDING FRONT OIL SEAL, V-BELT NEED TO CHANGE UN-EVEN TENSION.

2) MACH. No. 3 NC1-80(2) S/N 10208-8797 – TUC OIL LEAKS AT REAR OIL SEAL, RECOMMENDATION NEED TUC OVERHAUL, S/B SOL. VALVE AD-04/00E AIR LEAKS, AND V-BELT UN-EVEN TENSION NEED CHANGE.

Measures 3) MACH. No. 5 NC1-80(2) S/N 00208-7119 – SLIDE PARALLELISM NEED ADJUSTMENT, AND BOLSTER NEED PARALLELISM CHECK. GRIND ROUGH SURFACE

-6	0
0	+12

NOTE: ALL THIS MACHINE STILL CAN USE, BUT NEED CLOSE MONITORING THE OIL LEVEL OF FLYWHEEL FOR NO 1 & 3

Date	Man	Dep	AIDA	Arv	Cus	Dep	Cus	Arv	AIDA	Normal	1½	2	Job Done by
04/7/16		7	00	8	10	10	30	11	30	2			RHEY

SPARE PART	Qty	U/Price	Amount	Remark
LABOUR CHARGES [NORMAL]	2	US$ 25	US$ 50	
[1½]				Authorised / Confirm / Incharge
[2]				
TRANSPORT	1	US$ 25	US$ 25	
PACKING & DELIVERY CHARGE				
VAT				
TOTAL			US$ 75	

Work carried out to our complete satisfaction

CHARGEABLE

Checked & confirmed by
Name ERWIN GAMBOA
Post SR. ENGINEER
Sign
Date 07-04-16

Company Name/Stamp

AIDA GREATER ASIA PHILIPPINES, INC.

CUSTOMER COPY