NPI MACHINERY, INC.

5TH FLOOR, ORCELL II BUILDING
1611 QUEZON AVENUE, WEST TRIANGLE
QUEZON CITY 1100
TEL. NOS.: 925-17-03 926-74-79; 926-4683
FAX NOS.: 926-30-96

№ 4584

SERVICE REPORT

DATE January 17, 2024

CUSTOMER'S NAME PRICOM MICROELECTRONICS INC. | CUST. SIGNATURE

ADDRESS ECP LISP I CABUYAO LAGUNA

SERVICE BY BILLY J. GODOY | SERVICE MAN SIGN

1) REPAIR ☐	2) EXAMINATION ☐	3) OVERHAUL ☐	4) FITTING ☐	5) SUPERVISION OF START UP ☑

ACTION TAKEN MODEL: EXG - 150 SN: T-003465
- INSTALLATION OF SPARE ROBOT ON MC-15 KISSEI (UH1000-80)
- CONNECT ALL WIRINGS, TEST AND CHECK FUNCTION, REPLACE NG SENSOR
- CHECK AND TEST INTERLOCK CONNECTION, TEST RUN AND AUTO MODE

REMARKS: ROBOT IS READY FOR OPERATION

RESULT	1) OPERATING WELL	2) OPERATION UNABLE TO BE CHECKED	3) REPAIR WORK REMAINING TO BE DONE

PARTS USED

	PART CODE	NAME OF PART	QTY	UNIT PRICE	AMOUNT
1					
2					
3					
4					
5					
	LABOR CHARGE				
				LABOR AMOUNT	₱ 7,200.00

TIME STARTED 10:00	TIME FINISHED 16:00	TOTAL TIME 5 HRS	TRAVEL TIME

NPI Machinery Inc
5th Floor , ORCELL 2 Building,
1611 Quezon Avenue, West Triangle,
Quezon City 1100 Philippines

Telephone Nos: (632) 926-7479

Faximile No.: (632) 920-3096

DATE 23-Jan-2020

SERVICE QUOTATION

TO **PRICON MICROELECTRONICS INC.,**

NPISQ NO2020-01-004-1

ADDRESS No. 14 Ampere Street, Barangay Diezmo, Light Industry and Science Park1 (LISP 1), Cabuyao,

ATTENTION

Dear
We are honored to offer our services as follows for the following:

Machine Model EXG-150 Serial No T-003465

Brief Description of the Trouble or the Work to be done

Installation of spare robot on M/C 15 (UH1000-80 Nissei).
Connect all wirings, test and check function, replaced N.G. Sensor.
Check and test interlock connection, test run and auto mode.
Remarks: Robot is ready for operation.

Special Instructions

Service Report No. 4584 dated January 17, 2020

Machine Type	Working Task	Fee/task	Task	Line Total
EXG-150	Service Fee	7,200.00 P/task	1 task	7,200.00 P
			Total	7,200.00 P

Respectfully Yours
for: Jon Diaz