NPI MACHINERY, INC.

5TH FLOOR, ORCELL II BUILDING
1611 QUEZON AVENUE, WEST TRIANGLE
QUEZON CITY 1100
TEL. NOS.: 925-17-03 926-74-79; 926-4683
FAX NOS.: 926-30-96

№ 4562

SERVICE REPORT

DATE MAR 7 2018

CUSTOMER'S NAME PRICON MICROELECTRONICS INC

CUST. SIGNATURE

ADDRESS LOT 1 CABUYAO LAGUNA

SERVICE BY MELVIN D. MORALLA

SERVICE MAN SIGN

1) REPAIR ☑	2) EXAMINATION ☐	3) OVERHAUL ☐	4) FITTING ☐	5) SUPERVISION OF START UP ☐

ACTION TAKEN MODEL: FX 60 T-002946 MC NO. 16
- CONTROLLER OFF WHEN CONNECT ROBOT INTERFACE.
- FOUND WIRING SHORTED ON I/O REPLACE NEW I/O SENSOR.
- REPLACE SUB GRIPPER CYLINDER SLEW.
- NOW ROBOT IS OKAY AND CAN RUN AUTO.

RESULT	1) OPERATING WELL	2) OPERATION UNABLE TO BE CHECKED	3) REPAIR WORK REMAINING TO BE DONE

PARTS USED

	PART CODE	NAME OF PART	QTY	UNIT PRICE	AMOUNT
1					
2					
3					
4					
5					
	LABOR CHARGE				
				LABOR AMOUNT	₱ 4,800

TIME STARTED	TIME FINISHED	TOTAL TIME	TRAVEL TIME
12:30	15:30	3HRS	

NPI Machinery Inc
5th Floor , ORCELL 2 Building,
1611 Quezon Avenue, West Triangle,
Quezon City 1100 Philippines

Telephone Nos: (632) 926-7479

Faximile No.: (632) 920-3096

DATE 08-Mar-18

SERVICE QUOTATION

TO **PRICON MICROELECTRONICS INC.,**

NPISQ NO2018-03-006-1

ADDRESS No. 14 Ampere Street, Barangay Diezmo, Light Industry and Science Park1 (LISP 1), Cabuyao, Laguna

ATTENTION **Ms. Rebecca Valenzuela**

Dear Ms. Rebecca Valenzuela
We are honored to offer our services as follows for the following:

Machine Model EX-60 Serial No T-002346

Brief Description of the Trouble or the Work to be done

MC# 16 Controller off when connect robot interface. Found wiring shorted on LS4 replace new LS4 sensor. Replace sub gripper cylinder seal. Now robot is okay and can run auto.

Special Instructions

Service Report No. 4562 dated March 7, 2018

Machine Type	Working Task	Fee/task	Task	Line Total
EX-60	SERVICE FEE	4,800.00 P/task	1 task	4,800.00 P
			Total	4,800.00 P

Respectfully Yours

Jon Diaz