# NPI MACHINERY, INC.

5TH FLOOR, ORCELL II BUILDING
1611 QUEZON AVENUE, WEST TRIANGLE
QUEZON CITY 1100
TEL. NOS.: 925-17-03 926-74-79; 926-4683
FAX NOS.: 926-30-96


№ 4564

DATE APR - 5 2018

## SERVICE REPORT

| | | | | |
|---|---|---|---|---|
| CUSTOMER'S NAME | PRICON MICROELECTRONICS INC. | | CUST. SIGNATURE | 4/5/18 |
| ADDRESS | NO. 14 AMPERE ST. LIGHT INDUSTRY & SCIENCE PARK 1 BRGY. DILIGNO CABUYAO LAGUNA | | | |
| SERVICE BY | MELVIN D. MORCILLA | | SERVICE MAN SIGN | |
| 1) REPAIR ☑ | 2) EXAMINATION ☐ | 3) OVERHAUL ☐ | 4) FITTING ☑ | 5) SUPERVISION OF START UP ☐ |

ACTION TAKEN MODEL: EX-60 SN. T-003345
- ROBOT CANNOT OPERATE FIND OUT J3.1 CONTINUE ON. AND WIRING TERMINAL INSIDE CONTROLLER WAS DISCONNECTED (ON).
- REVERSE SPOON INSIDE ARM 30. CORRECT POSITION.
- FINISHED REPAIR & CONTROLLER AND NOW ROBOT IS OPERATIONAL.

| RESULT | 1) OPERATING WELL | 2) OPERATION UNABLE TO BE CHECKED | 3) REPAIR WORK REMAINING TO BE DONE |
|---|---|---|---|

PARTS USED

| | PART CODE | NAME OF PART | QTY | UNIT PRICE | AMOUNT |
|---|---|---|---|---|---|
| 1 | | CONTROLLER # 1 FINISHED REPAIR | | | |
| 2 | | CONTROLLER # 1 AND NOW OPERATIONAL. | | | |
| 3 | | | | | |
| 4 | | | | | |
| 5 | | | | | |
| | | | | | |
| | LABOR CHARGE | | | | |
| | | | | LABOR AMOUNT | ₱ 6,400 |

| TIME STARTED | TIME FINISHED | TOTAL TIME | TRAVEL TIME |
|---|---|---|---|
| 1:00 | 13:20 | 4 HRS | |

NPI Machinery Inc
5th Floor , ORCELL 2 Building,
1611 Quezon Avenue, West Triangle,
Quezon City 1100 Philippines

Telephone Nos: ( 632 ) 926-7479

Faximile No.: ( 632 ) 920-3096

DATE 06-Apr-18

**SERVICE QUOTATION**

TO **PRICON MICROELECTRONICS INC.,**

**NPISQ NO2018-04-007-1**

ADDRESS No. 14 Ampere Street, Barangay Diezmo, Light Industry and Science Park1 (LISP 1), Cabuyao, Laguna



ATTENTION **Ms. Rebecca Valenzuela**

Dear Ms. Rebecca Valenzuela
We are honored to offer our services as follows for the following:

Machine Model EX-60 Serial No T-002345

Brief Description of the Trouble or the Work to be done

Robot cannot operate find out LS4 continue on and wiring terminal inside controller was discontinued (OV). Reverse spoon inside RCH 20 correct position. Finished repair 2 controller and now robot is operational.

Special Instructions

Service Report No. 4564 dated April 5, 2018 .

| Machine Type | Working Task | Fee/task | Task | Line Total |
|---|---|---|---|---|
| EX-60 | SERVICE FEE | 6,400.00 P/task | 1 task | 6,400.00 P |
| | | | Total | 6,400.00 P |

Respectfully Yours

Jon Diaz