NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase7
Laguna Technopark-SEZ, Biñan, Laguna Tel. No.: (049) 544-5670 Fax No: (049) 544-5647

西沢

SERVICE REPORT

No.: A 0110

Customer: PRICON MICROELECTRONICS CORP.

Date: 7 / 14 / 2016

Model: PN60 - 5AN

Mfg. yy/mm: 2010 . 11

Serial Number: E0061000IK1

Gts.:

Controller: TACT

Reason for Maintenance

1) Oil temperature very high "60°C" because ASCC charge unable to finish.

Action Taken

1) Change ASCC charging speed.

SERVICE BY:

1 . Quiñones / T. Concepcion

2 N. Nishizawa

TIME:

Start	End
4 : 30	5 : 30

Total: 1 Hours

7/14/16

Authorized Signature

Service Fee: ₱ 4,000

Illustration

SQ No. PO No. SI No. OR No.

NPPIS010

(2) Agent