NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase7
Laguna Technopark-SEZ, Biñan, Laguna Tel. No.: (049) 544-5670 Fax No: (049) 544-5647

SERVICE REPORT

No.: A 0268

Customer: PRICON MICROELECTRONICS INC, **Date:** 10 / 27 / 16

Model: UH1000-40 **Mfg. yy/mm:** 1996.9

Serial Number: P04R005 **Gts.:** 12186633

Controller: 93T

Reason for Maintenance

1) Abnormal injection process (Screw ~~was~~ has abnormal backward movement when in Neutral position)

Action Taken

1) Changed Encoder and Base of Encoder

SERVICE BY:

1 B. Quiñones

2 N. Nishizawa

TIME:

Start	End
13 : 30	17 : 00

Total: 3.5 Hours

Authorized Signature

Service Fee: ₱ 11,500

Illustration

SQ No. _____ PO No. _____ SI No. _____ OR No. _____