NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase7
Laguna Technopark-SEZ, Biñan, Laguna Tel. No.: (049) 544-5670 Fax No: (049) 544-5647

SERVICE REPORT

No.: A 0463

Customer: PRICON MICROELECTRONICS, INC **Date:** 05 / 12 / 17

Model: FN1000 MC #: 9A **Mfg. yy/mm:** 1996.4

Serial Number: S0860398 **Gts.:** 214269|

Controller: NC 9000 G

Reason for Maintenance

1) Machine can't Heat-up (Barrel)

Action Taken

1) Machine Inspection:
- No signal received on "R8 - terminal #01 and #80 (Mold #1 Thermocouple)
- Found out that thermocouple of Mold #01 was uninstalled.
- Installed Jump Cable on Mold 1 terminals.

SERVICE BY:

1 B. Quiñones

2 N. Nishizawa

TIME:

Start	End
11 : 00	12 : 00

Total: 1 Hours

Authorized Signature

Service Fee: ₱ 7,000

Illustration

Note:

~~Thermocouple~~ Thermocouple was uninstalled in Mold #1, standard (~~Thermal~~) is thermocouple installed.

SQ No. _____ PO No. _____ SI No. _____ OR No. _____