NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase7
Laguna Technopark-SEZ, Biñan, Laguna Tel. No.: (049) 544-5670 Fax No: (049) 544-5647

SERVICE REPORT

No.: A 0895

Customer: PRICON MICROELECTRONICS INC. **Date:** 03 / 13 /2016

Model: FE80S12H **Mfg. yy/mm:** 1995. a

Serial Number: P08Q011 M/C #:16. **Gts.:** 2756908

Controller: NC93

Reason for Maintenance

- NO EJECTOR BACKWARD (MANUAL TEST)

Action Taken

- CHECK THE DIAGNOS FOR INPUT & OUTPUT
  - NO INPUT
- CHECK THE CAM SWITCH
  - FOUND OUT THAT ONE WIRE FOR COMMON CONNECTION WAS DISCONNECTED
- INSTALL THE WIRE PROPERLY
- MANUAL TEST OKAY / AUTO TEST OKAY

SERVICE BY:

1 R. EAMON

2 N. UICHANCO

TIME:

Start	End
16 : 00	17 : 00

Total: 1 Hou

Authorized Signature

Service Fee: ₱ 4,000.00

Illustration

SQ No. _____ PO No. _____ SI No. _____ OR No. _____