NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase7
Laguna Technopark-SEZ, Biñan, Laguna Tel. No.: (049) 544-5670 Fax No: (049) 544-5647

SERVICE REPORT

No.: A 0996

Customer: PRICON MICROELECTRONICS, INC. **Date:** 05 / 11 / 2018

Model: PN40-5H **Mfg. yy/mm:** 2004.09

Serial Number: P042010 M/C #: 5A **Gts.:** 9057806

Controller: NC9300T

Reason for Maintenance

- NO CONTROL OF SCREW SPEED
- NO SCREW FWD
- NOZZLE LEAK

Action Taken

- ADJUST INJ. RSN PRESSURE ON SERVO VALVE
- REPLACED NEW CHECK VALVE FOR SCREW FWD
- REPLACED TWO SETS OF INJECTION CARRIAGE CYLINDER PACKING SET
- MANUAL TEST OKAY
- AUTO TEST WITH PRODUCT
- M/C CAN PROCEED FOR MASS PRO.

SERVICE BY:

1 R. RAMON

2 _____

TIME:

Start	End
001 : 30	13 : 50

Total: 4H & 30 min ~~Hour~~

RIPPLE MARTINEZ
Authorized Signature

Service Fee: ₱ 20,000

Illustration

SQ No. _____ PO No. _____ SI No. _____ OR No. _____