NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 1804

Customer: PRICON MICROELECTRONICS INC. **Date:** 03 / 28 / 19

Model: PN40-5H **Machine no.** #6A **Mfg. yy/mm:** 2004.09

Serial Number: P04Z011 **Gts.:** 9843247

Controller: NC9300T **M/C Service Requested By:** SIR VER

Reason for Service / Machine Problem

> MACHINE CHECKING (ALARM OF ~~23050~~ 53050 : POSITION SENSOR COMMUNICATION LINE ERROR .2)

Action Taken

> CHECKED ENCODER POSITION : CLAMPING / EJECTOR / INJECTION
> CALIBRATE POSITION (ENCODER) FOR INJECTION
> MACHINE TRIAL / RUNNING
> NO ALARM ENCOUNTERED
> FOR MONITORING DURING RUNNING C/O CUSTOMER

** REMARKS :

> CHECKED INJECTION UNIT / RAM PACKING AREA HAVE OIL LEAK
- RECOMMEND TO CHANGE PACKING SEAL SET

SERVICE BY:

1 X. RAMIREZ 3 _____

2 _____ 4 _____

TIME:

Start	End
11 : 00	14 : 00

Total: 2 hrs. — mins.

REDDIE T. [illegible]
Authorized Customer Name & Signature

Service Fee: Php 7,000.00

Recommendation/Parts for Quotation

> PACKING SEAL SET FOR INJECTION RAM