NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2439

Customer: PRICON MICROELECTRONICS INC. **Date:** 01 / 06 / 20

Model: PN40 - 5# **Machine no.** 17A **Mfg. yy/mm:** 2004. 9

Serial Number: P04 2009 **Gts.:** 10 251 504

Controller: NC9300T **M/C Service Requested By:** SIR HENRY

Reason for Service / Machine Problem

CUSTOMER REQUEST FOR MACHINE CHECKING (MOLD AND ROBOT INTERLOCK)

Action Taken

> CONDUCT MANUAL RUNNING OF ROBOT AND MOLD (CLOSE AND OPEN) OKAY
> CONDUCT CHECKING OF ~~SAME~~ ELECTRICAL CONNECTIONS ON DIAGNOS ~~OKAY~~
IF "121" HAVE INPUT - OKAY. CUSTOMIZE
> FOUND OUT CUSTOMER ~~JUMPER~~ THE INTERLOCK CONNECTION THEY USE OTHER JUMPER CONNECTION FOR INTERLOCK
> NISSEI RECOMMEND TO CUSTOMER TO REMOVE THE ORIGINAL CONNECTION FOR EJECTOR PLATE BWD STOP AND USE ONLY THEIR CUSTOMIZE CONNECTION FOR SAFETY.
> MACHINE CAN RUN
> FOR MONITORING

SERVICE BY:

1 N. NISHIZAWA 3 F. CHING

2 X. RAMIREZ 4

Henry Guzman

Authorized Customer Name & Signature

TIME:

Start	End
11 : 30	13[illegible] : 30

Total: 2 [illegible] hrs. — mins.

Service Fee: Php 7,000.00

Recommendation/Parts for Quotation